



All Components

July 12
27257A
11-1

Customer: Zancor Homes (Wasaga) Site: Wasaga
Ltd.

Lot: 27

- Notes:
- ✓ KITCHEN:
 - ✓ -Supply & Install (1) Shelf for BC110 (White Melamine) ✓
 - ✓ -Supply & Install (1) Shelf for BC130 (White Melamine) ✓

+ CUTLERY ✓

DAVE

All above service items have been completed.

Date Completed: JUL 12, 2022

New Image Kitchens Representative: _____

Homeowner Representative: _____

Client Representative: _____

Name

Signature

LOT 27 CABINET Q0

MASTER ENITE

LAMINATE CHIPPED @ SIDE SPLASH (BROKEN)

CHIPS INSIDE BOTTOM OF LEFT BOX

" " " " RIGHT "

BUMPER REQ'D @ FAR RIGHT BOX

SMALL CHIP ON RIGHT SIDE OF COUNTER

NEED PH. OF APPROXIMATE DONE

DONE

MAIN BATH

CHIP ON LEFT SIDE OF COUNTER

SMALL CHIP INSIDE BOTTOM OF BOX

" " ON SIDE SPLASH

DONE

LAUNDRY

OK

KITCHEN

SCREW COVERS REQ'D INSIDE FRIDGE UPPER

CHIPS ON SIDE OF COUNTER @ FRIDGE OPENING

UPPER BOX LEFT OF FRIDGE - SCREW COVERS REQ'D

" " " " " CHIPS ON SHELVES

CHIP @ TOP SHELF - UPPER, FAR LEFT OF FRIDGE

UPPER BOX RIGHT OF STOVE - CHIPPED ALL @ TOP

" " " " " SCREW COVERS REQ'D

SCREW COVERS REQ'D @ STOVE UPPER

* & UPPER LEFT OF STOVE

UPPER BOX LEFT OF STOVE - SCREW COVERS & CHIPPED SHELVES

UPPER FAR LEFT " " " "

PENINSULA BRKT SIDE PANEL - CHIPS @ TOP

CHIPS @ DW PANEL

SINK BOX DAMAGED @ BOTTOM INSIDE & NEED SCREW COVERS

SHELF REQ'D @ LOWER LEFT OF STOVE & LEFT OF FRIDGE

* NEED CUTLERY TRAY

ADJUST ALL DOORS & DRAWERS

DONE

* MISSING VALET BOX 110 & BOX 130