Enrollment:

Purchaser Name: Velalagan Rajendram

Saranka Rajendram

Phone Res:

Phone Bus: (647) 291-6961 Closing Date: July 14, 2022 ZANCOR HOMES PDI Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 1 (Block 1) / 1

Plan: Address: Municiaplity:

Inspection Date: July 13, 2022

Inspector: Gisella Fiore Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
SINK/FAUCET/PLUMBING	PLUMBING NOT COMPLETE AT ISLAND/ MASTER ENSUITE/ MAIN BATH	
CABINETS	ADJUST KICKPLATE RIGHT OF STOVE	
COUNTERTOPS	SMALL CHIP RIGHT OF HOOD FAN BY PLUG AT BACKSPLASH	
WALLS	DRYWALL SEAM VISIBLE LEFT OF ISLAND	
BEDROOM 2 ENSUITE		
MIRROR	MIRROR NOT INSTALLED THROUGHOUT	
COUNTERTOPS	WHITE SCUFF INFRONT OF SINK	
EXTERIOR		
RAILING	NOT INSTALLED AT REAR OF HOME	
GARAGE DOORS	NOT INSTALLED	
NOTE:	DOWNSPOUT NOT INSTALLED	
	AC NOT INSTALLED	
MASTER ENSUITE BATH		
VANITY CABINETS	GABLE RIGHT OF SINK PEELING	
MASTER BEDROOM		
WALLS	CUT IN STIPPLE BY ATTIC HATCH	
FOYER/HALL		
STAIRS	EXPOSED SCREWS BELOW NOSING AT RISER AT STAIRS FROM 3RD FLOOR TO 2ND FLOOR	
	CHIP ON 6TH TREAD BY PICKET AT STAIRS FROM 2ND FLOOR TOO 3RD FLOOR BY RAILING	
	VARNISH REQUIRED AT NOSING AT STAIRS FROM MAIN FLOOR TO 1ST FLOOR	
	CRACK ON OUTSIDE STRINGER AT STAIRS FROM MAIN FLOOR TOO 2ND FLOOR	

Enrollment:

Purchaser Name: Velalagan Rajendram

Saranka Rajendram

Phone Res:

Phone Bus: (647) 291-6961
Closing Date: July 14, 2022
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 1 (Block 1) / 1

Plan: Address: Municiaplity:

Inspection Date: July 13, 2022

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. R. Velalage Velalagan Rajendram Saranka Rajendram Purchaser's Signature Purchaser's Signature Purchaser's Name (print) Purchaser's Name (print) Gisella Fiore Designate's Signature Inspector's Name (print) Inspector's Signature Designate's Name (print) July 13, 2022 Date (YYYY/MM/DD) 2022/07/13