



ZANCOR Zancor Homes (Brampton) Ltd. Warranty Services

Phone: (905) 738-7010 Fax: (905) 738-5948

Closing Date: Address: Location: Today's Date Contact(s): Email: Company: Attention: Telephone:	tion: Reserve Of Country Trails - Phase: 1 - Lot: 7 y's Date: 11Aug22 act(s): I: pany: Princeston Painting tion: Joe Macri					
Fax: Please Comp	lete the fo	llowing items:				
DAI	Туре	Issue		Appt. Date/Time	Notes	
149338	PDI	EXTERIOR- NOTE:~DENT ON RIGHT FRONT DOOR				
149356	PDI	FOYER/HALL- STAIRS~VARNISH REQUIRED AT TRIM RIGHT OF OUTSIDE STRINGER BY STAIRS TO BASEMENT / VARNISH DRIP MARK ON TREAD ABOVE LANDING TO BASEMENT STAIR / VARNISH CHIP ON TREAD AT STAIRS TO BASEMENT ABOVE LANDING				
Date Compl	leted:		Homeowner Signature: The Homeowner acknowledges and accepts all whas been completed in a workman like manner.			
Date Completed:				&/or Service	Tech.	

Signature:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.


Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Reserve Of Country Trails - Phase: 1 - Lot: 7

149338 - 1 - NOTE:~DENT ON RIGHT FRONT DOOR



149356 - 1 - STAIRS~VARNISH REQUIRED AT TRIM RIGHT OF OUTSIDE STRINGER BY STAIRS TO BASEMENT / VARNISH DRIP MARK ON TREAD ABOVE LANDING TO BASEMENT STAIR / VARNISH CHIP ON TREAD AT STAIRS TO BASEMENT ABOVE LANDING



149356 - 2 - STAIRS~VARNISH REQUIRED AT TRIM RIGHT OF OUTSIDE STRINGER BY STAIRS TO BASEMENT / VARNISH DRIP MARK ON TREAD ABOVE LANDING TO BASEMENT STAIR / VARNISH CHIP ON TREAD AT STAIRS TO BASEMENT ABOVE LANDING



149356 - 3 - STAIRS~VARNISH REQUIRED AT TRIM RIGHT OF OUTSIDE STRINGER BY STAIRS TO BASEMENT / VARNISH DRIP MARK ON TREAD ABOVE LANDING TO BASEMENT STAIR / VARNISH CHIP ON TREAD AT STAIRS TO BASEMENT ABOVE LANDING

