




Quality Sterling Group

22A

LC 114

REPAIR ORDER
711041



BC

REPRINT 1

BUILDER: Zancor Homes

JOB SITE:

Caledon Club

Customer Code:

Job Number:

18338 Board Area:8

COMPLAINT DATE: 08/02/22

LOT:

22A

INSTALLER:

SCHEDULED DATE: 08/15/22

(12-4)

OWNER NAME:

OWNER TEL:

905-731-4443

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE:

PDI

REPAIRMAN:

BUILDER WO#

149123+149131

BUILDER PO#:

PO Required:

NO

Inspection Reqd:

NO

ORIGINAL WO#:

701919

REPAIR DESC:

Main bathroom - shim required at ensuite

Bed 4 - carpet shim required

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

[Signature]

SUPER'S/OWNER'S SIGNATURE:

[Signature]

DATE:

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



NEAR EYE
PROTECTION



RESPIRATORY
PROTECTION



HEARING
PROTECTION



FALL
PROTECTION



ELECTRICAL
SAFETY



MATERIAL
HANDLING



MATERIAL
HANDLING



MATERIAL
HANDLING



MATERIAL
HANDLING



MATERIAL
HANDLING