

	ā
Lot	ILEIIIS
#	nsted
8	below
A	were
1	released
	Ö
Site	the
Site/Phase: _	ife Itellis listed below were released to the homeowner
Caledon	ner (s) of

Purchaser	he above items were received on this 8 day of	V/A Other	N/A Recycling and Green Bins	Homeowner Manual	TOHouse and Garage Door Keys
Purchaser	August ,2022				

Enrollment: Purchaser Name:

Navdeep Singh Kaul

Phone Res:
Phone Bus: (647) 629-7980
Closing Date: August 18, 2022
Inspector: Gisella Flore

MANCOR

HOMES

Vendor / Builder:
Project: Zancor Homes (Caledon) Ltd.
Lot / Phase: 118A / 1
Plan:

Address:

Municiaplity: Inspection Date: August 12, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

- DAMAGED, INCOMPLETE OR MISSING

 Windows, side lights and other glazing. Window and door screens

 Bathrub sinks and toilets

 Bathroom accessories if provided

 Mirrors, counter tops and cabinetry

 Floring (hardwood, viryl, ceramic tiles, carpeting)

 Interior finished and trim carpentry

 Furnace

 Hot water heater, if provided (not rental)

 Exterior finished, driveways, walkways, decks and landscaping

- OPERATING CONDITION

 Windows, interior and exterior doors. Door locks
 Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures
 Gas fireplaces, incl.circulation fans, if provided
 Heat Recovery Ventilation system, if provided
 Heating system
 Air conditioning system, if provided and if conditions

VANITY CABINETS	MASTER ENSUITE BATH	FRONT DOORS	WALLS		FLOORING	STAIRS	FOYER/HALL	000000000000000000000000000000000000000	FIOORING	CABINETS		KITCHEN	WINDOWS	LIVING ROOM			PORCH	RAILING	DECK	GARAGE DOORS	EXTERIOR	
CHIP INSIDE LOWER LEFT CABINET AT BOTTOM GABLE		CHIPS ON OPERATING DOOR AT SIDE ABOVE HINGE	BOWED WALL RIGHT SIDE OF MAIN HALL BOWED WALL RIGHT SIDE OF MAIN HALL	SCRATCH ON 3RD PLANK FROM KITCHEN INFRONT OF STAIRS	CHIP ON 2ND HARDWOOD PLANK INFRONT OF STAIRS TOO 2ND FLOOR	CHIP ON JRD RISER AT STAIRS TO 1ST LANDING TO 2ND FLOOR		OF DEWOVE WARNS FHOM FLOOR BELOW SINK ISLAND	CHIP / CRACK INSIDE UPPER CABINET AT LEFT GABLE LEFT OF HOOD FAN	CHIP INSIDE LOWER CABINET RIGHT OF FRIDGE AT GABLE	CHIP ON LEFT ISLAND GABLE		SCRATCH / CRACK ON BALCONY SLIDING GLASS		SCRATCH ON TOP TRIM ABOVE OPERATING DOOR	CHIP ON FRONT PORCH	DENT ON SIDING CEILING AT FRONT PORCH	NOT INSTALLED AT FRONT PORCH	PLANKS NOT INSTALLED AT BEDROOM BALCONY	NOT INSTALLED		Supplied and a condition of the control of the cont
	- Cooper		002	000		-	- Annual Control of the Control of t	1 200				Material Section of Control of Co						THE PARTY	2027			ovided allo il conditions pen
		1	E	¥	The state of the s			S						***************************************						1		THE

Purchaser Name: Navdeep Singh Kaul

Phone Res:
Phone Bus: (647) 629-7980
Closing Date: August 18, 2022
Inspector: Glosfia Flore

HOMES ANCOR

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.
Lot / Phase: 118A / 1
Plan:

Address:

Municiaplity: Inspection Date: August 12, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS), Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

- DAMAGED, INCOMPLETE OR MISSING

 Windows, side lights and other glazing. Window and door screens

 Bathtub sinks and toilets

 Bathroom accessories if provided

 Mirrors, counter tops and cabinetry

 Flooring (hardwood, vinyl, ceramic tiles, carpeting)

 Interior finished and trim carpentry

 Furnace

- Furnace Hot water heater, if provided (not rental) Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION Windows, Interior and exterior doors, Door locks Faucets: Kitchen, bathroom, laundry room Exhaust fans (Richen, bathrooms) if provided Electrical outlets and fixtures Gas flreplaces, incl.circulation fans, if provided Heat Recovery Ventilation system, if provided Heating system Alr conditioning system, if provided and if conditions permit

	Γ	7					Г	1			Г	7	Г	7						_
VANITY CABINETS	MASTER ENSUITE BATH	FRONT DOORS	WALLS	:	FLOORING	STAIRS	FOYER/HALL	FLOORING	CABINETS		KITCHEN	WINDOWS	LIVING ROOM			PORCH	RAILING	DECK	GARAGE DOORS	EXTEMOR
CHIP INSIDE LOWER LEFT CABINET AT BOTTOM GABLE		CHIPS ON OPERATING DOOR AT SIDE ABOVE HINGE	CHIP ON 6TH AND 7TH PLANK AT FLOOR INFRONT OF BASEMENT STAIRS	SCRATCH ON 3RD PLANK FROM KITCHEN INFRONT OF STAIRS	CHIP ON INSIDE STRINGER LEFT SIDE AT STAIRS TO BASEMENT BY 1ST TREAD	CHIP ON 3RD RISER AT STAIRS TO 1ST LANDING TO 2ND FLOOR	A LA LA CALLA CALL	CHIP / CRACK INSIDE UPPER CABINET AT LEFT GABLE LEFT OF HOOD FAN. PEMOVE MARKS FROM FLOOR BELOW SINK ISLAND.	CHIP INSIDE LOWER CABINET RIGHT OF FRIDGE AT GABLE	CHIP ON LEFT ISLAND GABLE		SCRATCH / CRACK ON BALCONY SLIDING GLASS		SCRATCH ON TOP TRIM ABOVE OPERATING DOOR	CHIP ON FRONT PORCH	DENT ON SIDING CEILING AT FRONT PORCH	NOT INSTALLED AT FRONT PORCH	PLANKS NOT INSTALLED AT BEDROOM BAT CONV	NOT INSTALLED	
	DOT	Don					1 200-4								description and a state of the description of the state o		20	ST.		
															Application of the state of the					