Enrollment:

Purchaser Name: Muhammad Salman Khawaja

Zeb, Salman Khawaja

Phone Res:

Phone Bus: (647) 409-1962 Closing Date: August 25, 2022 Inspector: Gisella Fiore

HOMES

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 52 (Block 9) / 1

Plan: Address: Municiaplity:

Inspection Date: August 23, 2022

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH			
MIRROR	SHOWER GLASS NOT INSTALLED AND MIRROR THROUGHOUT	 	
VANITY CABINETS	RIGHT GABLE PEELING AT CORNER	 	
	ADJUST BANK OF DRAWERS HARD TO OPEN AND CLOSE	 	
MASTER BEDROOM			
FLOORING	CARPET NOT INSTALLED THROUGHOUT 3RD FLOOR BED ROOM	 	
WALK IN CLOSET	WIRED SHELVING NOT INSTALLED THROUGHOUT	 	
FOYER/HALL			
STAIRS	DAMAGED RISER BELOW NOSING AT 3RD FLOOR 2) DAMAGED TREAD ABOVE LANDING AT	 	
	STAIRS TOO 2ND FLOOR 3) CHIPS ON 1ST TREAD AT 1ST FLOOR TOO 2ND FLOOR		
KITCHEN			
COUNTERTOPS	COUNTERTOP NOT INSTALLED AT KITCHEN	 	
SINK/FAUCET/PLUMBING	SINK NOT INSTALLED AT SURVERY	 	
CABINETS	ADJUST PANTRY LEFT OFF FRIDGE HARD TO OPEN AND CLOSE AND AT POT DRAWER RIGHT OF	 	
	FRIDGE		
	CHIP ON 2ND BANK OF DRAWER AND INSTALL SHELVE RIGHT SIDE	 	
	CHIP ON LOWER LEFT DOOR LEFT OF DISHWASHER AT ISLAND	 	
LIVING ROOM			
WALLS	TRIM NOT INSTALLED AROUND BALCONY DOORS AT MAIN FLOOR	 	
WINDOWS	WINDOW SCREEN NOT INSTALLED LEFT OF BALCONY DOOR	 	
EXTERIOR			
GARAGE DOORS	GARAGE DOOR DOES NOT LOCK		
PORCH	EAVESTROUGH NOT INSTALLED	 	

Enrollment:

Purchaser Name: Muhammad Salman Khawaja

Zeb, Salman Khawaja

Phone Res:

Phone Bus: (647) 409-1962 Closing Date: August 25, 2022 Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Purchaser's Signature

Lot / Phase: Unit 52 (Block 9) / 1

Plan: Address: Municiaplity:

Inspection Date: August 23, 2022

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the

designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Muhammad Salman Khawaja

Zeb, Salman Khawaja

Purchaser's Signature Purchaser's Name (print) Purchaser's Name (print)

Gisella Fiore

Designate's Signature Inspector's Name (print) Designate's Name (print) Inspector's Signature

August 23, 2022 Date (YYYY/MM/DD) 2022/08/23