## MANCOR

hei
-
Ė
3
items li
-
3
ed
isted below were
0
€
≶
e
æ
3
<u>e</u>
ea
Se
a
released to
À
the h
0
ĭ
me
0
2
<u></u>
7
<u>(S</u>
0
4

Lot #	
Site/Phase:	
Caledon	
Brangeran	

II House and Garage Door Keys

ZHomeowner Manual

N/A Recycling and Green Bins

N/A Other Rolling Rad + Fire Place R

The above items were received on this 22 day of ,2022

Purchaser

Purchaser

Simceler

CALEDON

Enrollment:

Purchaser Name: Phone Res: Raminder Singh Simerjeet Kaur

Closing Date: August 18, 2022 Inspector: Gisella Flore

Phone Bus:

ANCOR HOMES

Vendor / Builder:
Project:
Lot / Phase:

Zancor Homes (Brampton) Ltd.

Plan: 7/1

Address:

Municiaplity: Inspection Date: August 22, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

- DAMAGED, INCOMPLETE OR MISSING

  Windows, side lights and other glazing. Window and door screens

  Bathrub sinks and foliets

  Bathroom accessories if provided

  Mirrors, counter tops and cabinetry

  Floring flandwood, viryl, ceramic tiles, carpeting)

  Interior finished and tim carpentry

  Furnace

  Hot water heater, if provided (not rental)

  Exterior finished, driveways, walkways, decks and landscaping

- OPERATING CONDITION

  Windows, interior and exterior doors. Door locks
  Faucets: Kitchen, bathroom, laundry room
  Exhaust fans (lighten, bathrooms) if provided
  Electrical outlets and fixtures
  Gas freplaces, incl.circulation fans, if provided
  Heat Recovery Venillation system, if provided
  Heatring system
  Hot water heater, if provided (not rental)
  Air conditioning system, if provided and if conditions permit

VANITY CABINETS	BEDROOM 3 ENSUITE	FLOORING	BEDROOM #3	COUNTERTOPS	BEDROOM 2 ENSUITE	TOILET	COUNTERTOPS	MACTED SINCIPLE DATE	CABINETS	KITCHEN		STAIRS		FRONT DOORS	FOYER/HALL
GABLE RIGHT SIDE AT FLOOR LIFTED		DEBRIS UNDER CARPET BELOW WINDOW		REMOVE GLUE/PENCIL MARKS FROM COUNTERTOP IN SHARED BATH SCRATCH ON SIDE SPLASH LEFT SIDE SHARED BATH		LOWER LEFT CABINET BELOW RIGHT SINK  SMALL CHIP AT BOTTOM RIGHT GABLE INSIDE CABINET INSPECT TOILET FOR DEBRIS / SECURE CEILING FAN AT TOILET ROOM	REMOVE PAINT OR INSPECT FOR SCRATCH ON LOWER RIGHT CABINET BELOW LEFT SINK AND		— STAIN DRIP ON LOWER BANK OF DRAWERS RIGHT OF STOVE AND BELOW SINK LEFT DOOR  LARGE SCRATCH ON RIGHT ISLAND GABLE RIGHT OF SINK AND CHIP ON LEFT SIDE  A DUIST GARBAGE DRAWER AND 3RD BANK OF DRAWER  "CHIP ON LOWER CABINET LEFT OF POT DRAWER  "SCRATCH / STAIN ON LOWER POT DRAWER  "SCRATCH / STAIN ON LOWER POT DRAWER		STAIRS TO BASEMENT, CRACK ON INSIDE STRINGER BY TREAD AT STAIRS TO BASEMENT ABOVE LANDING / CHIP ON 1ST TREAD AT STAIRS TO BASEMENT ABOVE LANDING / CHIP ON 1ST TREAD AT STAIRS FROM MUD ROOM TO MAIN FLOOR / CHIP ON RIGHT INSIDE STRINGER AT STAIRS FROM FOVER TO MAIN FLOOR BY 2ND TREAD SMALL CHIP ON NEWEL POST TO 2ND FLOOR / CRACK BY PLUG AT UPPER RAILING / CHIP ON RAILING AT MAIN FLOOR BY NEWEL POST TO BASEMENT / CHIP ON TRIM AT LEFT SIDE ABOVE TREAD AT STAIRS FROM BASEMENT TO 1ST LANDING / CHIP ON NEWEL POST BASEMENT VARNISH REQUIRED AT TRIM RIGHT OF OUTSIDE STRINGER BY STAIRS TO BASEMENT / VARNISH DRIP MARK ON TREAD ABOVE LANDING TO BASEMENT STAIR / VARNISH CHIP ON TREAD AT STAIRS TO BASEMENT ABOVE LANDING	REMOVE RAILS AT AT RISER BELOW NOSING AT 2ND FLOOR / CHIP ON INSIDE STRINGER BY	TOUCH UP ASTRICAL AT FRONT DOOR	ADJUST FRONT DOOR CANNOT CLOSE PROPERLY	
DOZE				Man Allenda		Den	Dar.	College of the state	A P P P P P P P P P P P P P P P P P P P					DODE.	
VIK				SK		NV.	AS							X . X	

Enrollment: Purchaser Name: Raminder Singh Simerjeet Kaur

Phone Bus:
Closing Date: August 18, 2022
Inspector: Gisella Flore Phone Res:

HOMES

Page 2 of 2

Vendor/Builder:
Project: Zancor Homes (Brampton) Ltd.
Lot / Phase: 7 / 1
Plan:

Address:
Municiapity:
Inspection Date: August 22, 2022

NOTE:	EXTERIOR	WALLS	POWDER ROOM	FLOORING	NOTE:	LIVING ROOM
SCREEN RIPPED BASEMENT WINDOW RIGHT SIDE REMOVE WOOD LEFT SIDE OF HOUSE AT BRICK REMOVE WHITE PAINT FROM GARAGE TRIM RIGHT SIDE DENT ON RIGHT FRONT DOOR		HOMEOWNER UNHAPPY WITH SWING OF DOOR TO POWDER, WOULD LIKE IT CHANGED LIKE LOT 3 AND 8 TO SWING OUT		CHIP IN HARDWOOD PLANK AT ENTRANCE TO LIVING FROM HALLWAY	REMOVE DEBRIS FROM INSIDE FIREPLACE	
Doz.					002-1	7
S S					N.S.	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

\*Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Date (YYYY/MM/DD) Purchaser's Name (print) Designate's Name (print) Raminder Singh Designate's Signature Purchaser's Signature Surphyllogu August 22, 2022 Inspector's Name (print) Gisella Fiore Purchaser's Name (print) Simerjeet Kaur Purchaser's Signature Inspector's Signature