



## Service Completion Status Report

**Zancor**

Date : Aug 22, 2022

Fax :

Phone :

**ZAN08 – ZANCOR HOMES (COOKSTOWN) LTD.**

Report To: Site

Lot Number	Work Description	Status Status Date	Builder Ref #
27	IMPERFECTIONS AND OPENINGS ARE OBSERVABLE AT MANY (APROX 100+) LOCATIONS AT THE BRICK MASONRY SYSTEM. A MASONRY RESTORATION EXPERT WILL BE REQUIRED TO MATCH THE COLOUR OF THE BRICK MORTAR WHEN CORRECTING THE OBVIOUS DEFICIENCY	Completed 07/29/2022	147705 S-064392
27	THE CRACK IN THE REAR FRENCH DOORS SILL SHOULD BE FORMALLY CUT AND SEALED, OR SEALED IN A VISUALLY ACCEPTABLE FASHION	Completed 07/13/2022	147709 S-064392