



Service Completion Status Report

Zancor

Date : Sep 9, 2022

Fax :

Phone :

ZAN10 - ZANCOR-670-672 WINONA DR.11-19

Report To: N/A

Lot Number	Work Description	Status Status Date	Builder Ref #
670	WINDOW SILLS NEED CLEANING. note: You may need to contact this homeowner for access. stevenwalt@gmail.com or 647-973-9258 notes: GTA washed full house	Completed 09/09/2022	146075-56 S-062817
670	BRICK BELOW FRONT DOOR HAS BEEN MORTAR ALL OVER. note: You may need to contact this homeowner for access. stevenwalt@gmail.com or 647-973-9258 notes: GTA washed full house	Completed 09/09/2022	146083-64 S-062817
670	FACE/EXTERIOR BRICK MORTAR HAS DISAPPEARED ABOVE THE MAIN WEST WINDOW. note: You may need to contact this homeowner for access. stevenwalt@gmail.com or 647-973-9258 ** Duplicate Item previously received on 10/14/2021. Builder Ref #: 146088. MG Service #: S-062650. **	Not Started	146088-69 S-062817