

9

Preet

First call

Sept 22

Key
Access

Done

Kitchen

- Marked small chips on Island
- Island shelf chipped @ corner
- Fridge enclosure chipped / fill nail holes
- Cabinet above fridge missing bumper / Shelves chipped
- Various chips marked on uppers / lowers / Shelves.
- Top drawer Right of Stove missing bumper
- Cabinet door left of fridge missing bumper. (Lower)
- Upper Cabinet left of fridge damaged @ back corner of shelf (whole joint)

Pantry

- bottom right cabinet missing shelf Anchor
- bottom right Tall cabinet door missing bumper
- Multiple chips @ cabinets / Shelves marked.

Laundry

- Wrong Counter top
- Right door missing bumper
- Chip @ bottom left of shelf
- Left inside edge is chipped along whole length.
- chip @ Top left corner of Vanity
- Chip @ Top of Right door

Done

Ensuite

- Chip @ bottom right by door (inside)
- Chip @ Left back edge (inside)

Shared Bath

- Marked chips on doors (x3)
- Inside edges of cabinets chipped (x3)

Master Ensuite

- Remove Fed Residue from Counter-top
- 3rd drawer from top missing bumpers.
- Left Sink
 - ↳ Right door chipped @ inside
 - ↳ Chipped @ inside of Vanity
- Right sink
 - ↳ Right door chipped.