

148

Preet

~~Sept 16~~

Key Access

Sept 22

Done

Kitchen Q.C.

Kitchen

- Chip @ Fridge enclosure
- upper Right of Fridge - Door chipped
- Corner upper cracked inside
- upper left of stove - Door chipped
- cabinet above stove - Doors chipped (x2)
- Top drawer Right of stove chipped
- Cabinet under sink chipped
- Fill nail holes behind dishwasher

Master Ensuite

Main Bath

- Chip on Right side of Vanity

Laundry

- Scratch on door