



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W159631  
Pack Slip:197428

Service Date: Oct 11, 2022

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000508 City: WHITBY Received: May 11, 2022  
Name: ZANCOR WHITBY Service Phone(s): Time:  
Service Fax: Site Phone: Order: D374324-1  
Site Fax: Lot#: BLK 4 - 26 Phase: PH1

RESIDENT INFORMATION

Home Owner Name: RYAN, MICHAEL IABONI Address: 2 LAKE TRAIL WAY  
Home Phone(s): Work Phone(s):  
Cell Phone(s): Email(s): ryan@rwm.ca

LINKED ORDER INFORMATION (D374324-1)

Customer: N000508 ZANCOR WHITBY Lot #: BLK 4 - 26  
Model: TH-3 / EXT END (LOT 26) Phase: PH1

SERVICE INSTRUCTIONS

CHANGE SVPD (LINE: 170 MB) FROM LEFT TO RIGHT

ADD:

MASTER BEDROOM- WINDOWS-AS PER HOMEOWNER SLIDING DOOR SHOULD BE ON OTHER SIDE HEAT REGISTER IN FRONT OF DOOR.

LIVING ROOM- WIND OWS-SHATTERED FIXED RIGHT WINDOW. *done*

LIBRARY/DEN- WINDOWS-BALCONY DOOR GLASS CRACKED.

SASH AND GLASS NOT DONE NEED THE PO TO GO IN TO LOT 39 *done*

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
216	NEWMAR VINYL CASEMENT COMPLETED	GRT	GLASS ONLY - SASH	18.75 X 56.75	AG13 BK/WH LOWE_ARG BK	1
340	BUCKINGHAM PURCH. PATIO DOOR po 78061	REC	SASH AND GLASS	X	LEFT BK CLR LOWE_ARG	1
555	NEWMAR VINYL CASEMENT FIXED	GRT	GLASS ONLY - FIXED	48.75 X 56.75	CLR LOWE_ARG 4mm GLASS REQD BK	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ 1332

Labour \$ 120

P.O.#:

Cause:

*Sash and glass already done*

Solution:

Date Completed: OCT 11-2022

Approved: \_\_\_\_\_

Time: \_\_\_\_\_

Service Signature: \_\_\_\_\_

  
ZAHER  
*Zaher*



FU

NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

Confirmed

WO # W159631  
Pack Slip:197428

Service Date: Aug 02, 2022

Priority: Normal Status: SCHEDULED RELEASED

**BUILDER**

Customer: N000508 City: WHITBY Received: May 11, 2022

Name: ZANCOR WHITBY Service Phone(s): Time:

Service Fax: Site Phone: Order: D374324-1

Site Fax: Lot#: BLK 4 - 26 Phase: PH1

**RESIDENT INFORMATION**

Home Owner Name: Address:

Home Phone(s): Work Phone(s):

Cell Phone(s): Email(s):

**LINKED ORDER INFORMATION (D374324-1)**

Customer: N000508 ZANCOR WHITBY Lot #: BLK 4 - 26

Model: TH-3 / EXT END (LOT 26) Phase: PH1

**SERVICE INSTRUCTIONS**

CHANGE SVPD (LINE: 170 MB) FROM LEFT TO RIGHT *COMP*

ADD:  
MASTER BEDROOM- WINDOWS-AS PER HOMEOWNER SLIDING DOOR SHOULD BE ON OTHER SIDE HEAT REGISTER IN FRONT OF DOOR. *COMP*

LIVING ROOM- WIND OWS-SHATTERED FIXED RIGHT WINDOW *UND 48 3/4 X 56 3/4 CLEAR*

LIBRARY/DEN- WINDOWS-BALCONY DOOR GLASS CRACKED. *COMP*

SASH AND GLASS NOT DONE NEED THE PO TO GO IN TO LOT 39

**PARTS REQUIRED**

LN	Item Description	Location	Specification	Size	Options	Qty
216	NEWMAR VINYL CASEMENT	GRT	GLASS ONLY - SASH	18.75 X 56.75	AG13 BK/WH LOWE_ARG BK	1
340	BUCKINGHAM PURCH. PATIO DOOR	REC	SASH AND GLASS	X	LEFT BK CLR LOWE_ARG	1

*NOT USED*

Problem Description: \_\_\_\_\_

☐ Warranty

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

☐ CHARGEABLES

Material \$ *KAYMAN*

Labour \$ *416 791 9862*

P.O.#:

Cause: \_\_\_\_\_

Solution: \_\_\_\_\_

Date Completed: \_\_\_\_\_

Approved: \_\_\_\_\_

Time: \_\_\_\_\_

Service Signature: \_\_\_\_\_

LUIS



Maniraj Mavoori Nagaraj &lt;mmnagaraj@newmar.com&gt;

**Fwd: N000508 ZANCOR WHITBY / SWO's**

1 message

Christina Pellegrini <cpellegrini@newmar.com>  
 To: Maniraj Mavoori Nagaraj <mmnagaraj@newmar.com>

Wed, May 11, 2022 at 12:48 PM

Let me know when you are about to start this..I will come by

----- Forwarded message -----

From: Mathew Harant <mharant@newmar.com>  
 Date: Wed, May 11, 2022 at 12:44 PM  
 Subject: N000508 ZANCOR WHITBY / SWO's  
 To: Christina Pellegrini <cpellegrini@newmar.com>

Hey,

Can you please have the following SWO's created:

D374314 / BLK 3 - 16 - Change SVPD (line: 150 MB) from right to LEFT (nothing needs to be ordered).  
 D374318 / BLK 3 - 20 - Change SVPD (line: 140 MB) from left to RIGHT (nothing needs to be ordered).  
 D374319 / BLK 4 - 21 - Change SVPD (line: 140 MB) from right to LEFT (nothing needs to be ordered).  
 D374324 / BLK 4 - 26 - Change SVPD (line: 170 MB) from left to RIGHT (nothing needs to be ordered).  
 D374325 / BLK 5 - 27 - Change SVPD (line: 120 MB) from left to RIGHT (nothing needs to be ordered).  
 D374331 / BLK 5 - 33 - SVPD in rec room (line: 100) needs to be a LEFT (it is currently a right), the SVPD in BKF (line: 110) needs to be a RIGHT (it is currently a left) - Please just swap the sashes. Also change SVPD (line: 140 MB) from left to RIGHT (nothing needs to be ordered).  
 D374332 / BLK 6 - 34 - Change SVPD (line: 140 MB) from right to LEFT (nothing needs to be ordered).  
 D374336 / BLK 6 - 38 - Change SVPD (line: 150 MB) from left to RIGHT (nothing needs to be ordered).  
 D374342 / BLK 8 - 44 - Change SVPD (line: 140 MB) from right to LEFT (nothing needs to be ordered).  
 D374348 / BLK 8 - 50 - Change SVPD (line: 150 MB) from left to RIGHT (nothing needs to be ordered).

Thank you,

**Mathew Harant**  
**Sales Account Manager**

**Newmar Window Manufacturing Inc.**

7630 Airport Road  
 Mississauga, Ontario L4T 4G6  
 Tel: 905-672-1233  
 Fax: 905-672-1076  
 Toll Free: 1-800-263-5634  
 www.newmar.com

Click here for information on Newmar Aluminum Window Wall systems

**Manufacturers of Quality Windows and Entrance Door Systems**

Please consider the environment before printing this email.

*This e-mail and any attachments may contain information that is privileged and/or confidential. If you are not the intended recipient and appear to have received this e-mail in error, please notify us immediately and then delete all copies from your computer system. Any unauthorized use, copying or further distribution is prohibited. Please also note that if you send us e-mails containing time-sensitive or important instructions, you should ensure that receipt has been timely acknowledged in view of the potential for misdirection or inadvertent interception. Thank you*

Christina



**Zancor Homes (Parkview) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 23Jun22

**Address:**

**Location:** Now Towns In Brooklin - Phase: 1 - Lot: Unit 26 (Block 4)

**Today's Date:** 18May22

**Contact(s):**

**Email:**

**Company:** Newmar

**Attention:** Alex

**Telephone:** (905) 672-1233

**Fax:** (905) 672-6350

**Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
147834	PDI	MASTER BEDROOM- WINDOWS~AS PER HOMEOWNER SLIDING DOOR SHOULD BE ON OTHER SIDE HEAT REGISTER IN FRONT OF DOOR			
147837	PDI	LIVING ROOM- WIND OWS~SHATTERED FIXED RIGHT WINDOW			
147838	PDI	LIBRARY/DEN- WINDOWS~BALCON Y DOOR GLASS CRACKED			

**Date Completed:** OCT 11-2022

**Homeowner Signature:** 

The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

**Date Completed:** OCT 11-2022

**Trade &/or Service Tech.**

**Signature:** 


Print Name: \_\_\_\_\_

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.


**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

**Now Towns In Brooklin - Phase: 1 - Lot: Unit 26 (Block 4)**

**147834 - 1 - WINDOWS~AS PER HOMEOWNER  
SLIDING DOOR SHOULD BE ON OTHER SIDE  
HEAT REGISTER IN FRONT OF DOOR**



**147837 - 1 - WINDOWS~SHATTERED FIXED RIGHT  
WINDOW**



**147838 - 1 - WINDOWS~BALCONY DOOR GLASS  
CRACKED**

