



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W159631
Pack Slip:197428
Service Date: Oct 11, 2022

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000508 City: WHITBY Received: May 11, 2022

Name: ZANCOR WHITBY Service Phone(s): Time: Order: D374324-1

Service Fax: Site Phone: Lot#: BLK 4 - 26 Phase: PH1

Site Fax: Lot#: BLK 4 - 26

RESIDENT INFORMATION

Home Owner Name: RYAN, MICHAEL IABONI

Home Phone(s): Address: 2 LAKE TRAIL WAY

Cell Phone(s): Work Phone(s): Email(s): ryan@rwm.ca

LINKED ORDER INFORMATION (D374324-1)

Customer: N000508 ZANCOR WHITBY Lot #: BLK 4 - 26

Model: TH-3 / EXT END (LOT 26) Phase: PH1

SERVICE INSTRUCTIONS

CHANGE SVPD (LINE: 170 MB) FROM LEFT TO RIGHT

ADD:

MASTER BEDROOM- WINDOWS-AS PER HOMEOWNER SLIDING DOOR SHOULD BE ON OTHER SIDE HEAT REGISTER IN FRONT OF DOOR.

LIVING ROOM- WIND OWS-SHATTERED FIXED RIGHT WINDOW. *done*

LIBRARY/DEN- WINDOWS-BALCONY DOOR GLASS CRACKED.

SASH AND GLASS NOT DONE NEED THE PO TO GO IN TO LOT 39 *done*

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
216	NEWMAR VINYL CASEMENT COMPLETED	GRT	GLASS ONLY - SASH	18.75 X 56.75	AG13 BK/WH LOWE_ARG BK	1
340	BUCKINGHAM PURCH. PATIO DOOR REC po 78061	REC	SASH AND GLASS	X	LEFT BK CLR LOWE_ARG	1
555	NEWMAR VINYL CASEMENT FIXED	GRT	GLASS ONLY - FIXED	48.75 X 56.75	CLR LOWE_ARG 4mm GLASS REQD BK	1

Problem Description:

☐ Warranty ☐ CHARGEABLES

Material \$ Material \$ 1332

Labour \$ Labour \$ 170

P.O.#:

Cause:

Sash and glass already done

Solution:

Date Completed: OCT 11-2022

Approved: _____

Time: _____

Service Signature: _____


ZAHER



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

Confirmed
WO # W159631
Pack Slip: 197428
Service Date: Aug 02, 2022

Priority: Normal
BUILDER
Customer: N000508
Name: ZANCOR WHITBY
Service Fax:
Site Fax:
Status: SCHEDULED
City: WHITBY
Service Phone(s):
Site Phone:
Lot#: BLK 4 - 26
Received: May 11, 2022
Time:
Order: D374324-1
Phase: PH1
RELEASED

RESIDENT INFORMATION

Home Owner Name:
Home Phone(s):
Cell Phone(s):
Address:
Work Phone(s):
Email(s):

LINKED ORDER INFORMATION (D374324-1)

Customer: N000508 ZANCOR WHITBY
Model: TH-3 / EXT END (LOT 26)

Lot #: BLK 4 - 26
Phase: PH1

SERVICE INSTRUCTIONS

CHANGE SVPD (LINE: 170 MB) FROM LEFT TO RIGHT *Comp*

ADD:

MASTER BEDROOM- WINDOWS-AS PER HOMEOWNER SLIDING DOOR SHOULD BE ON OTHER SIDE HEAT REGISTER IN FRONT OF DOOR. *Comp*

LIVING ROOM- WIND OWS-SHATTERED FIXED RIGHT WINDOW *48" x 56" CLEAR*

LIBRARY/DEN- WINDOWS-BALCONY DOOR GLASS CRACKED. *Comp*

SASH AND GLASS NOT DONE NEED THE PO TO GO IN TO LOT 39

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
216	NEWMAR VINYL CASEMENT	GRT	GLASS ONLY - SASH	18.75 X 56.75	AG13 BKWH LOWE_ARG BK	1
340	BUCKINGHAM PURCH. PATIO DOOR REC COMPLETED	REC	SASH AND GLASS	X	LEFT BK CLR LOWE_ARG	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed: _____

Approved: _____

Closing Date: 23Jun22

Address:
Location: Now Towns In Brooklyn - Phase: 1 - Lot: Unit 26 (Block 4)
Today's Date: 18May22
Contact(s):
Email:

Company: Newmar
Attention: Alex
Telephone: (905) 672-1233
Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
147834	PDI	MASTER BEDROOM-WINDOWS~AS PER HOMEOWNER SLIDING DOOR SHOULD BE ON OTHER SIDE HEAT REGISTER IN FRONT OF DOOR		
147837	PDI	LIVING ROOM- WINDOWS~SHATTERED FIXED RIGHT WINDOW		
147838	PDI	LIBRARY/DEN-WINDOWS~BALCON Y DOOR GLASS CRACKED		

Date Completed: 05/11/2022 Homeowner Signature: [Signature]
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: 05/11/2022 Trade &/or Service Tech. Signature: [Signature]