



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W156513
Pack Slip:197729
Service Date: Apr 28, 2022

Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000508 City: WHITBY Received: Mar 30, 2022

Name: ZANCOR WHITBY Service Phone(s): Time:

Service Fax: Site Phone: Order: D374326-1

Site Fax: Lot#: BLK 5 - 28 Phase: PH1

RESIDENT INFORMATION

Home Owner Name: Address:

Home Phone(s): Work Phone(s):

Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D374326-1)

Customer: N000508 ZANCOR WHITBY Lot #: BLK 5 - 28

Model: TH-2 Phase: PH1

SERVICE INSTRUCTIONS

FOYER/HALL- FRONT DOORS-BUBBLE ON BOTTOM OF DOOR LEFT SIDE

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
92	2' 10" CLAD DOOR SYS BUBBLE ON BOTTOM OF DOOR LEFT SIDE	ENT	OTHER RPLCMNT PARTS	37.25 X 97.75	BK 61316 FJ RIGHT 2' 10" CLAD DOOR SYS	1
93	NO DOOR LIGHT SELECTED	ENT				1

Problem Description: Nothing to do with Newmar

☐ Warranty

☐ CHARGEABLES

Material \$ N/A

Labour \$ N/A

P.O.#:

Cause:

Solution: site signature

Date Completed: April 28/22 Approved: [Signature]

Time: 1520 Service Signature: [Signature] STEVE