



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W166010

Pack Slip:224592

Service Date: Oct 14, 2022

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Aug 23, 2022
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D388437-1
Site Fax: Lot#: 152W Phase:

RESIDENT INFORMATION

Home Owner Name: Address: 1335 BRODERICK STREET,
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D388437-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 152W
Model: 36-04 CUNNINGHAM OP 4BD+(OP STD)/SW/LOT 152W Phase:

SERVICE INSTRUCTIONS

LINE 40 (RR/GRT) MISSING RIGHT SASH (AS PER INSTALL REPORT)

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
44	NEWMAR VINYL CASEMENT	RR/GRT	SASH AND GLASS	28.125 X 54.125	RIGHT SW CLR LOWE_ARG	1

Problem Description: MISSING

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution: REPLACEMENT

SITE SUPER - SIGNATURE

Date Completed: OCT 14 2022

Approved: NATHAN SIMS

Time:

Service Signature: RAY



Christina Pellegrini <cpellegrini@newmar.com>

***IS* D388437-1 Lot 152W - ZANCOR BELLE AIRE SHORES - 611313**

1 message

COPS <cops@newmar.com>

Mon, Aug 22, 2022 at 4:50 PM

Reply-To: Tesorowindows@bellnet.ca

To: cpellegrini@newmar.com



INSTALL SERVICE EMAIL REQUIREDInstall
Required

In Progress

Install
Completed

BRICKLAYERS "NOTE":

A clearance of **1/4"** must be left on both sides and top of the frame and
1/2" (first floor) **1"** (second floor) on bottom of frames.

Contact **Newmar** for bottom clearances above two floors.

WARNING! Failure to adhere to the above voids all performance warranties

First Install: Thursday August 18, 2022**Last Install: Thursday August 18, 2022****Installer's Name:**

D388437-1 611313 - ZANCOR BELLE AIRE SHORES**Sl's ID: 0038****Lot / Phase: 152W /****House Model: 36-04 CUNNINGHAM OP 4BD+**
(OP STD)/SW/LOT 152W**Elevation: A****Pack Slip#: 224592**

Line Count Summary**Pieces to Load: 1****Openings Count: 1**

8/23/22, 9:27 AM

Newmar / Casa Bella Mail - *IS* D388437-1 Lot 152W - ZANCOR BELLE AIRE SHORES - 611313

Outstanding: 1

Installed: 0

Not Installed: 0

Backordered: 0

Cancelled: 0

Site Joins: 0

INSTALLATION ITEMS

LN #40 / ITEM P4

QTY: 1 **INSTALLED** (confirmed)

LOCATION: RR/GRT

SIZE: 120 X 56 **SWING:** F/L/F/F/R

OPTIONS: 61316 SW CLR

NOTES: Missing right sash

Notes Saved On: Aug 22, 2022 04:50:25 pm

(Email Sent to Sales Rep)

NEWMAR WINDOW MFG. INC.

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6