

Zancor Homes (Block 81) Ltd. **Warranty Services**

Phone: (905) 738-7010 Fax: (905) 738-5948

Work Order

WESTMOUNT SEND P/W Compression

| Closing | Date: | 21May21 |
|---------|-------|--|
| Closing | Dute. | The state of the s |

Address:

32 Tatton Court

King City, Ontario

Location:

The Village at Kings Ridge - Phase: 1 - Lot: Block 4 Unit 19

Today's Date:

18Aug21

Contact(s):

Matthew, Paul Vanelli - Cell: (647) 505-8172

Chantelle, Bianca Vanelli - Cell: (647) 505-8172

Email:

mattvanelli@gmail.com

Company:

Uni-tri

Attention:

Joey/Jason

Telephone:

(416) 745-2724

Fax:

(416) 745-1375

| DAI | Туре | Issue | Appt. Date/Time | Notes |
|--------|--------|---|-----------------|-------------|
| 145518 | 30-Day | Exterior- General- Item #4-Damage window sill at left side of house | 03Sep21 /am | Arrival 9am |
| 145519 | 30-Day | Exterior- General- Item #5- Remove motar off bricks | 03Sep21 /am | Arrival 9am |
| 145520 | 30-Day | Exterior- General- Item #6- Chipped brick at back of house right side (right of window corner) | 03Sep21 /am | Arrival 9am |

| Date Completed: | Homeowner Signature: |
|-----------------|---|
| | The Homeowner acknowledges and accepts all work |
| | has been completed in a workman like manner. |

Date Completed: APA 25 2022

Trade &/or Service Tech.

Signature: Whi

Print Name: KEN BIRON

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and Uni-Tri Masonry (1989) Limited 23 Haas Road Etobicoke, ON M9W 3A1 Telephone: (416) 745-2724

Telephone: (416) 745-272 Fax: (416) 745-1375

Serviceman Signature:

White: Office

WORK ORDER 12589

Pink: Site

EXTRA TO CONTRACT

| Builder: | ZANCORE |
|----------|-----------------------|
| Project: | VILLAGE AT KNUS RIDGE |
| Lot No. | BLOCK Y UNIT 19 |
| Address: | 32 TATTON COURT |

| Builder Ref: | Description of Work To Be Completed | Description of Work Performed | Time |
|--------------------------------|--|---|------------|
| 145518 | - DAMAGED WINDOW | - SILL HAD LARGE CHIE | , |
| | SILL AT LEAT SIDE OF | I PATCHED THE ALEA | NEW |
| | HOUSE | CEMENT | |
| | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | |
| 145519 | - REMOVE MORTAR OFF | -X PRESSURE WASH | / |
| | BRICK | NEEDED (FRONT LOOK | SOK/BAC |
| | | AND SIDES NEED ! | 7) |
| | | | |
| 145520 | - CHIPPED BRICK AT | -TWO DAMAGED BE | RICK AT |
| BACIL | BACIL OF HOUSE | BACIL CORNER AS | 7 |
| | | AS TWO NEAR THE | IR PLUG |
| | | BOX. THESE WERE CO | 122LEO OL |
| Chargeable To: | | AND REPLACED Total Hours | 8 |
| | | WINEW BRILK | |
| | | | |
| Date Complete | d: APR 26 2012 | 3.0 % | |
| By signing this (1989) Limited | Work Order, I agree to all the information provided for the work performed (labour) and/or (labour & | ded above and authorize payment to Uni-T & materials). | ri Masonry |
| Superintenden | t Signature: | | |
| | 0- 1 | | |

Yellow: Service Department