



Anthony Sit-Sing
416) 791-9266

NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W168832
Pack Slip:211332

Service Date: Oct 24, 2022

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000531 City: CALEDON Received: Oct 04, 2022
Name: ZANCOR CALEDON CLUB Service Phone(s): Time: 10AM - 2PM
Service Fax: Site Phone: Order: D380145-1
Site Fax: Lot#: 60A Phase:

RESIDENT INFORMATION

Home Owner Name: HARISH K BASRA/ SONIA BASRA - Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): 647-286-3972, 647-286-3974 Email(s): basrahk@yahoo.com,
sonia_basra@yahoo.com

LINKED ORDER INFORMATION (D380145-1)

Customer: N000531 ZANCOR CALEDON CLUB Lot #: 60A
Model: 30-05 CAPILANO (STND + OPT. GROUND) (BK) Phase:

SERVICE INSTRUCTIONS

FRONT BEDROOM PRESSURE CRACK ON OP SIDE

ADD:
BEDROOM #3- WINDOWS-CRACK ON OPERATING WINDOW

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
131	NEWMAR VINYL CASEMENT	B4	GLASS ONLY - SASH	18.75 X 62.75	AG13 BK/WH LOWE_ARG BK	1

Problem Description: A/c Signed Backup

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ 134

Labour \$ 170

P.O.#:

Cause:

Solution:

Date Completed: Oct 24/22

Approved:

Time: 3:00 PM

Service Signature: STEVE



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 23Jun22

Address:

Location: Caledon Club - Phase: 1 - Lot: 60A

Today's Date: 17Oct22

Contact(s): Harish K Basra - Cell: (647) 286-3972 - (basrahk@yahoo.com)
Sonia Basra - Cell: (647) 286-3974 - (sonia_basra@yahoo.com)

Email: basrahk@yahoo.com

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
151122	PDI	BEDROOM #3- WINDOWS~CRACK ON OPERATING WINDOW			

Date Completed: _____

Homeowner Signature: Roni Datt
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: Oct 24/22

Trade &/or Service Tech.

Signature: Stevan Maica

Print Name: Stevan Maica

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Caledon Club - Phase: 1 - Lot: 60A

**151122 - 1 - WINDOWS~CRACK ON OPERATING
WINDOW**





Service Department <servicedept@newmar.com>

Fwd: Caledon Club Lot 60

1 message

Ana Rodrigues <arodrigues@casabellawindows.ca>

Thu, Sep 29, 2022 at 8:04 AM

To: Service Department <servicedept@newmar.com>, Service Department <service@newmar.com>

----- Forwarded message -----

From: **Anthony Petta** <APetta@zancorhomes.com>


Date: Thu, Sep 29, 2022 at 8:00 AM

Subject: Caledon Club Lot 60

To: Ana Rodrigues <arodrigues@casabellawindows.ca>

Front bedroom pressure crack on OP side .





Sent from my iPhone

Ana Rodrigues
Customer Service Manager

All new service requests must be sent to servicedept@newmar.com

PLEASE NOTE - We are experiencing higher than normal volume and appreciate your patience as we review your inquiry, we are doing our best to respond back in a timely manner.

Ana Rodrigues
Casabella/Newmar
Customer Service manager

10/4/22, 12:13 PM

Newmar / Casa Bella Mail - Fwd: Caledon Club Lot 60



Casa Bella Windows Inc.
7630 Airport Road
Mississauga, Ontario L4T 4G6

Tel: 905-672-1233 ext 337
Fax: 416-650-5580
Toll Free: 1-800-407-9917

service@casabellawindows.ca

www.casabellawindows.ca