

119

Done

Kitchen Q.C.

Kitchen

Preet Oct 24 Key »

- For right lower - door chipped.
- Left Island cabinet chipped

Master Ensuite

Red residue @ backsplash.

Main Bath

Laundry