

115
Kitchen Q.C.

Oct 24
KEY Done
Access

Kitchen

- Island, under sink door chipped.
- Island, left cabinet chip inside
- Cabinet above Fridge - Shelf/cabinet chipped.
- Upper Cabinet left of Fridge - Adjust doors
 - Rough inside edges.
 - Cabinet chipped
- upper Cabinet left of Store - door chip @ Top
 - Rough inside edges.
- Top 2 drawers left of Store - No bumpers
- Lower Cabinet left of Store chipped on side.
- Lower Cabinet right of Store chipped on side.
- Adjust Feet left lower door.

Master Ensuite

- Left Sink Cabinet - Inside of door chipped.
 - Rough inside edges.
 - Cabinet chipped
- Bottom drawer face crooked.
- Right Sink Cabinet - Door chipped @ inside

Main Bath

- Left Side splash damaged
- Right door chipped @ inside
- under sink - Rough inside right edge
 - Doors chipped.

Left Bath

- Doors chipped.

www.PrintablePaper.net

Laundry

No Back/Side splash?