

Phone: (905) 738-7010 Fax: (905) 738-5948

Work Order

| CI | osina | Date: | 29Sep22 |
|----|-------|-------|---------|
| | | | |

Address:

Location: Now Towns In Brooklin - Phase: 1 - Lot: Unit 39 (Block 7)

Today's Date:

18Oct22

Contact(s):

Elango Pararajasingam - Cell: (647) 839-9947 - (erubigadevi@yahoo.com)

Thavakumar Ketharanathan - (thavakumar2019@outlook.com)

Email:

erubigadevi@yahoo.com

| Company: | Stairfal |
|----------|----------|
|----------|----------|

Attention:

Sam/Frank/Bruno/Ross/Damien

Telephone: Fax:

(416) 213-5771 (905) 895-9565



Please Complete the following items: DAI Type Issue Appt. Notes Date/Time 151213 PDI FOYER/HALL-STAIRS~OUTSIDE STRINGER AT STAIRS TO THE THIRD-FLOOR CUT SHORT CAN SEE FROM MAIN FLOOR.2) CHECK UP AT 1,6 7, 8 TREAD AT STAIRS FROM SECOND FLOOR TO THIRD FLOOR 3) **BLACK STAIRS ON** X2 TREAD BELOW NOSING AT LANDING TO 2ND FLOOR 4) REPLACE NOSING AT MUDROOM WATER DAMAGE.

| Date Completed: | Homeowner Signature: The Homeowner acknowledges and accepts all work | |
|-----------------|--|--|
| | has been completed in a workman like manner. | |
| Date Completed: | Trade &/or Service Tech. | |