

Zancor Homes (Caledon) Ltd. Warranty Services

Phone: (905) 738-7010 Fax: (905) 738-5948

**Work Order** 

Closing Date: 18Aug22

Address:

Location: Caledon Club - Phase: 1 - Lot: 107A 03Nov22

Today's Date:

Contact(s): Fraz Tabassam - Work: (647) 210-0667 - (fraztabassam@gmail.com) Igra Shahid - Work: (647) 293-5669 - (igrafraz24@gmail.com)

Email: fraztabassam@gmail.com

Company: Zancor -Caledon

Attention:

Telephone:

Fax:

Please Complete the following items:

Igen .		7	wood needs to be		
_	1,40ct22 /pm		Family Room- General- Item #28	30-Day	151026
Spen	/40ct22 /pm	7	Main Bathroom- General- Item #25 paint stains needs to be removed	30-Day	151023
Solar	/pm	1	General- Item #24 paint stains needs to be removed as noted on PDI		
	14Oct22		Main Bathroom-	30-Day	151022
Agen	/pm	7	#22 trim missing from landing to basement and mudroom -service to caulk at stringer	C Cay	
	4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		Chairs Conord Hom	30_Dav	151020
200	Medi	5	#20 mudroom - door stopper missing from mudroom door - service to install		
>	140ct22		Other- General- Item	30-Day	151017
Notes	Appt. Date/Time		Issue	Туре	DAI

151037	151036	151035	151034	151032	151031	151030	151028	151027
Interval	Interval	Interval	Interval	30-Day	30-Day	30-Day	30-Day	30-Day
Stairs- General- service spindles at stairs	Main Bathroom- General- service behind toilet at main bath	Main Bathroom- General- service caulk at tub in main bath	Stairs- General- service touch up wall above stairs	Exterior- General- Item #17 yard/side hose bib at side of home damaged -done	Kitchen- General- Item #33 backwall in kitchen pantry is cracked -service to patch	Powder Room- General- Item #32 vanity backwall damaged - service patch	Throughout- General- Item #30 on PDI day it was noted that touch up required on multiple different places like washrooms, room closets walls etc. builder put green tapes on all those areas, all of these areas still require touch ups	Master Ensuite- General- Item #29 hand shower connection in master bath is loose - service to caulk
140ct22 /pm	140ct22 /pm	140ct22 /pm	140ct22	/40ct22 /pm	140ct22 pm	/pm	14Oct22 /pm	140ct22 /ppi
Spor	Span	Som	You.	Son	Som	You	La Caración de la Car	You

151847	151039	151038
Interval	Interval	Interval
Foyer- General- service to caulk due to door replacement	Living Room- General- service to adjust vent living	Bedroom 3- General- service to touch up door by handle in office room (bedroom 3)
7	7	(
	140ct22 /pm	140ct22 /pm
Spore	Jon	Men

Date Completed: X 7-11-202

Date Completed: Mov 9 122

Homeowner Signature: X

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Signature:

Print Name:

appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. Please schedule your Service Department to complete work on the above Lot. Should no

it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and applied to the Company listed above.

## Caledon Club - Phase: 1 - Lot: 107A **Outstanding Deficiencies**

	Zancor - Add 14Oct22	ral- Item #20 mudroom - door	18 Ot	30-Дау	11 Oct22
id 140ct22	<u>AV</u> <u>Classic</u>   <u>Add</u> 151016	Main Bathroom- General- Item #18 dent on silver mold between tile and hardwood onted at PDI	17 on	30-Day	110ct22
Add 140ct22	National A	Bedroom 2- General- Item #14 inspect if air return required at bedroom by master bedroom	Be 14 air be	30-Day	110ct22
Add 140ct22	New Image Kitchens 151008	Kitchen- General- Item #9 cabinets and drawer handles needs to be gold K	9 Ki	30-Day	110ct22
<u>Add</u> <u>140ct22</u>	Perfect Touch Painting 151006	Stairs- General- Item #7 varnish required at nosing at main floor stairs to basement P.	7 Str	30-Day	110ct22
Add 140ct22	<u>AV</u> <u>Classic</u> 151000	Bedroom 2 Ensuite- General- Item #1 scratch on marble surround right side (noted on PDI)	1 sci (no	30-Day	110ct22
Add 140ct22	Perfect Touch Painting 150757	Stairs- General- Varnish required on stairs due to Bolton repair  P	9 Str	Interval	050ct22
<u>Add</u> <u>140ct22</u>	Perfect Touch Painting 150756	Stairs- General- Varnish required on stairs due to Bolton repair $\frac{\underline{F}}{1}$	8 St	Interval	050ct22
Add 140ct22	Perfect Touch Painting 149938	Foyer- General- Stain touch up required due to Bolton repair  1	3 Fo	Interval	09Sep22
<u>Add</u> <u>140ct22</u>	<u>Uni-tri</u> 149856	Exterior- General- Metal flashing missing on left side of house by poweder room 1	2 Ex	Interval	02Sep22
1 140c22	First Canadian Hardwood	Main Bathroom- General- Dent on silver t mold between tile and hardwood noted at walkthrough- FCH TO REMOVE THE FIRST PIECE OF HARDWOOD HERONT FIRST	M 1 ws FI	Interval	02Sep22
Add 060ct22	<u>AV</u> <u>Classic</u> 149855	Main Bathroom- General- Dent on silver t mold between tile and hardwood noted at walkthrough- FCH TO REMOVE THE FIRST PIECE OF HARDWOOD INFRONT FIRST	1 War B	Interval	02Sep22
Add 06Oct22	AV Classic 149463	MASTER ENSUITE BATH- SHOWER ENCLOSURE~SCRATCH ON MARBLE URROUND RIGHT SIDE	24 EI St	PDI	16Aug22
<u>Add</u> <u>140ct22</u>	Perfect Touch Painting 149455	FOYER/HALL- STAIRS~VARNISH REQUIRED AT NOSING AT MAIN FLOOR STAIRS TO BASEMENT	16 RU	PDI	16Aug22
Add 0	Integral Window Systems 149602	Basement- General- WINDOWS~SCREEN NOT INSTALLED IN BASEMENT WINDOWS  J	1 W W	PDI	16Aug22
Add Appointment Trade Date	Integral	A	Number	Туре	Reported

stopper missing from mudroom door- service to install  Shairs-General-Item #22 trim missing from landing to basement and mudroom - service to caulk at stringer  Shairs-General-Item #23 needs varnish on pDI  Main Bathroom-General-Item #24 paint stains needs to be removed as noted on pDI  Main Bathroom-General-Item #25 paint stains needs to be removed as noted on pDI  Stains needs to be removed  Kitchen-General-Item #26 canopy hood greasy patches issue. have multiple greasy patches  Kitchen-General-Item #27 cutout for the microwave drawer over needs to be frixed want piece of wood needs to be frixed shower connection in master bath is loose - service to caulk shower connection in master bath is loose - service to caulk at the mittiple different places like washrooms, room closets walls etc. buildar put green tapes on all those areas, all of these areas still require touch ups  Jo-Day  Jo-Day  Jo-Day  Steinen-General-Item #31 wooden floor on my index party is cracked -service patch loose  Schrein-General-Item #33 backwall in holes  Other-General-Item #31 wooden floor on both floors have some small holes - fill holes  Jo-Day  Jo	-																		
Setopper missing from mudroom door		110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	110ct22	
Stopper missing from mudroom door-  Stopper missing from mudroom door-  Statistics   Statistics   General-Item #23 timeds varnish on   Perfect multiple places after service man fixed   Touch issues on stairs and railing as noted on   Perfect multiple places after service man fixed   Painting   Main Bathroom- General-Item #25 paint   Caledon   Main Bathroom- General-Item #35 paint   Caledon   Main Bathroom- General-Item #37 cutout for the   Main Bathroom- General-Item #27 cutout for the   Main Bathroom- General-Item #28 minding   Main Bathroom- General-Item #28 minding   Main Bathroom- General-Item #29 hand   Main Bathroom- General-Item #30 on PDI   Master Ensuite- General-Item #31 wooden floor on   Caledon   Add   Main Bathroom- General-Item #33 backwall in   Marcon- General-Item #35 backwall in   Marcon- General-Item #37 backwall in   Marcon- General-Item #38 backwall in   Main Bathroom- General-Service to patch   Main Bathroom- General-Service eaulk at   Caledon   Add   Main Bathroom- General-Service behind   C		Interval	Interval	Interval	30-Day	30-Day	30-Day	30 <b>-D</b> ay	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	2
from mudroom door - Caledon   Caledo		14	13	12	ن 4	33	32	31	30	29	28	27	26	25	24	23	22	21	
Caledon   151017		Main Bathroom- General- service behind toilet at main bath		Stairs- General- service touch up wall above stairs	Exterior- General- Item #19 metal flashing missing on left side of house by powder room window at lentil	Exterior- General- Item #17 yard/side hose bib at side of home damaged -done	Kitchen- General- Item #33 backwall in kitchen pantry is cracked -service to patch		Other- General- Item #31 wooden floor on both floors have some small holes - fill holes	Throughout- General- Item #30 on PDI day it was noted that touch up required on multiple different places like washrooms, room closets walls etc. builder put green tapes on all those areas, all of these areas still require touch ups	Master Ensuite- General- Item #29 hand shower connection in master bath is loose - service to caulk	Family Room- General- Item #28 inside vent piece of wood needs to be trimmed	Kitchen- General- Item #27 cutout for the microwave drawer over needs to be fixed	Kitchen- General- Item #26 canopy hood greasy patches issue. have multiple greasy patches	Main Bathroom- General- Item #25 paint stains needs to be removed	Main Bathroom- General- Item #24 paint stains needs to be removed as noted on PDI	s- General- Item #23 needs varnish iple places after service man fixed so on stairs and railing as noted on	Stairs- General- Item #22 trim missing from landing to basement and mudroom service to caulk at stringer	stopper missing from mudroom door - service to install
Add         Add <th></th> <td>Zancor - Caledon 151036</td> <td>Zancor - Caledon 151035</td> <td>Zancor - Caledon 151034</td> <td>Promark Aluminum LTD. 151033</td> <td>Zancor - Caledon 151032</td> <td>Zancor - Caledon 151031</td> <td>Zancor - Caledon 151030</td> <td>First Canadian Hardwood 151029</td> <td>Zancor - Caledon 151028</td> <td>Zancor - Caledon 151027</td> <td>Zancor - Caledon 151026</td> <td>New Image Kitchens 151025</td> <td></td> <td>Zancor - Caledon 151023</td> <td>Zancor - Caledon 151022</td> <td></td> <td>Zancor - Caledon 151020</td> <td>st - User: Ale Caledon 151017</td>		Zancor - Caledon 151036	Zancor - Caledon 151035	Zancor - Caledon 151034	Promark Aluminum LTD. 151033	Zancor - Caledon 151032	Zancor - Caledon 151031	Zancor - Caledon 151030	First Canadian Hardwood 151029	Zancor - Caledon 151028	Zancor - Caledon 151027	Zancor - Caledon 151026	New Image Kitchens 151025		Zancor - Caledon 151023	Zancor - Caledon 151022		Zancor - Caledon 151020	st - User: Ale Caledon 151017
140ct22		Add	Add	Add	Add	Add	Add	Add		Add	Add	Add	Add	Add	Add	Add	Add		xandria
		140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	140ct22	Caledon   151017
李春春 梅春春		7	5	5		7	1	1			7	1			7	7		1	-
	1	Show	Lan	In	, ,	Jan C	Son a	4/~		16	A Company	12			Sal L	No.	Som	1/2	

100								
6		NoAppoint.	Add	Zancor - Caledon 151847	Foyer- General- service to caulk due to door replacement	22	Interval	03Nov22
Jan .		NoAppoint.	Add	Perfect Touch Painting 151620	Stairs- General- stain required at trim from landing to basement and mudroom due to via trim install	21	Interval	310ct22
		NoAppoint.	Add	<u>Uni-tri</u> 151415	Exterior- General- chipped brick left side of house	20	Interval	260ct22
		NoAppoint,	Add	Promark Aluminum LTD. 151414	Exterior- General- damage hardy board at upper left window due to scaffold	19	Interval	260ct22
		NoAppoint.	Add	Promark Aluminum LTD. 151413	Exterior- General- damage downspout left side of house due to scaffold	00	Interval	260ct22
3	7	140c22	Add	Zancor - Caledon 151039	Living Room- General- service to adjust vent living	17	Interval	110ct22
2	1	140ct22	Add	Zancor - Caledon 151038	Bedroom 3- General- service to touch up door by handle in office room (bedroom 3)	16	Interval	110ct22
200		Add   140ct22   ledon   1037	Add	Zancor - Caledon 151037	Stairs-General- service spindles at stairs	15	Interval	110ct22

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Zancor Service Technician: