Enrollment:

Purchaser Name: Sukhjit Kaur

Tirath Sidhu

Phone Res:

Phone Bus: (416) 844-5080

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 55A / 1

Plan: Address: Municiaplity:

Inspection Date: November 14, 2022

Closing Date: November 17, 2022 Inspector: Gisella Fiore

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

FOYER/HALL		
FRONT DOORS	OPERATING RIGHT DOOR DAMAGED AT BOTTOM SEE PHOTO	 
WINDOWS	RIGHT OPERATING WINDOW ADJUST FILLER PIECE NOT STRAIGHT	 
STAIRS	ADJUST PLUG AT UPPER RAILING	 
	PICKET AT UPPER LEFT SIDE BY WALL NOT STRAIGHT	 
	VARNISH TO REQUIRED AT RISER AT 1ST LANDING WHERE NAIL HOLES WERE FILLED	 
	CHIP AT OUTSIDE STRINGER BY NEWEL POST AT STAIRS AT MAIN FLOOR RIGHT SIDE	 
	CRACK AT INSIDE STRINGER BELOW NOSING AT STAIR TO BASEMENT	 
MASTER ENSUITE BATH		
NOTE:	TOLIET PAPER HOLDER AND TOWERS RACKS NOT INSTALLED	 
VANITY CABINETS	CHIPS AT KICKPLATE BELOW SINK	 
	CHIP BELOW RIGHT SINK RIGHT DOOR	 
MIRROR	MIRRORS THROUGHOUT NOT INSTALLED	 
MASTER BEDROOM		
NOTE:	BOWED WALL AT FIX WINDOW LEFT SIDE OF ROOM	 
BEDROOM 3 ENSUITE		
COUNTERTOPS	CRACKED SIDE OF COUNTERTOP RIGHT SIDE	 
KITCHEN		
CABINETS	REMOVE BLACK STAINS FROM UPPER RIGHT AND LEFT OR RIGHT OF HOOD FAN 2) REMOVE	 
	BLACK STAINS FROM LOWER LEFT CABINET AT ISLAND	
LIVING ROOM		
TRIM	AS PER HOMEOWNER INSPECT TRIM LEFT WALL FOR BEING BOWED AND DEN RIGHT SIDE3	 
ELECTRICAL/LIGHTING	SECURE FIREPLACE NOT FLUSH	 
EXTERIOR		
PAINT	FRONT DOOR NOT PAINTED	

Enrollment:

EXTERIOR

Purchaser Name: Sukhjit Kaur

Tirath Sidhu

Phone Res:

Phone Bus: (416) 844-5080 Closing Date: November 17, 2022 Inspector: Gisella Fiore

ZANCOR

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 55A / 1 Plan:

Address: Municiaplity:

Inspection Date: November 14, 2022

NOTE: EAVES AND DOWNSPOUT NOT COMPLETE	 

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

\* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the

designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

- Carable Tirath Sidhu Sukhjit Kaur

Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print)

Gisella Fiore

Designate's Name (print) Inspector's Name (print) Designate's Signature Inspector's Signature

Date (YYYY/MM/DD) 2022/11/14 November 14, 2022