

114
Kitchen Q.C.

Dap at
Bottom of
gable see
next page

Nov 28

Key

ACI

Access

Kitchen

- upper right of stove. ~~2 shelves chipped~~
- Stove upper. ~~ceiling chipped~~
- ~~Door chipped~~
- upper left of stove. ~~Doors chipped~~
- ~~Top shelf chipped~~
- ~~Rough inside edge~~
- ~~chips on Fridge enclosure~~
- Fridge upper. ~~Doors chipped~~
- ~~shelf chipped~~
- Pantry. ~~Shelves chipped~~
- ~~Door chipped~~
- Drawers. right of stove. ~~Adjust doors~~
- ~~chip on right side @ bottom~~
- ~~not soft close~~
- Kick cracked @ Island.
- ~~Left door missing @ Island~~
- Island cabinet door chipped.
- ~~Single drawer not soft close~~
- ~~Adjust doors~~

Master Ensuite

Main Bath

Lost Bath

~~Doors chipped~~

www.PrintablePaper.net

Laundry

- Vanity. Red residue on backsplash
- ~~Door chipped~~
- upper. ~~Door chipped~~

M