



Quality Sterling Group

*Gerry*

REPAIR ORDER

722137



BC

BUILDER: Zancor Homes

JOB SITE: Caledon Club

Customer Code:

Job Number: 18338 Board Area:8

COMPLAINT DATE: 11/17/22

LOT: 92A

INSTALLER:

SCHEDULED DATE: 11/29/22

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

*1-4*

ACCESS NOTES:

REPAIR TYPE: E-MAIL

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 701410

REPAIR DESC: adjust carpet shim at entrance to bath too high and carpet raised at right corner of window

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

SUPER'S/OWNER'S SIGNATURE:

DATE: *11/29/22*

**NOTE\*\*\* Please have this memo signed by the owner or site super upon completion.**

**WARNING**

THINK SAFETY - ALWAYS WEAR  
YOUR SAFETY SHOES AND HARDHAT



CLASS A  
Flammable  
Liquid



CLASS B  
Corrosive  
Liquid



CLASS C  
Compressed  
Gas



CLASS D  
Oxidizing  
Material



CLASS E  
Poisonous  
Material



CLASS F  
Radioactive  
Material



CLASS G  
Infectious  
Material



CLASS H  
Corrosive  
Material



CLASS I  
Corrosive  
Material



CLASS J  
Corrosive  
Material

INSTALLER SIGNATURE

DATE

722137

Patrick 11/17

Lot 92A



**Zancor Homes (Caledon) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order****Closing Date:** 17Nov22**Address:****Location:** Caledon Club - Phase: 1 - Lot: 92A**Today's Date:** 17Nov22**Contact(s):** Jaspreet Singh - Cell: (647) 376-4400 Work: (905) 297-9272 -  
(jaspreet402@gmail.com)**Email:** jaspreet402@gmail.com**Company:** Quality Rugs Canada LTD.**Attention:****Telephone:** (905) 731-4443**Fax:****Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
152123	PDI	Bedroom 3- General-FLOORING~ADJUST CARPET SHIM AT ENTRANCED TO BATH TOO HIGH AND CARPET RAISED AT RIGHT CORNER OF WINDOW			

Date Completed: \_\_\_\_\_

Homeowner Signature: \_\_\_\_\_

The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

Date Completed: \_\_\_\_\_

**Trade &/or Service Tech.**

Signature: \_\_\_\_\_

Print Name: \_\_\_\_\_


Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and**




**Caledon Club - Phase: 1 - Lot: 92A**

**152123 - 1 - FLOORING~ADJUST CARPET SHIM AT ENTRANCED TO BATH TOO HIGH AND CARPET RAISED AT RIGHT CORNER OF WINDOW**




**152123 - 2 - FLOORING~ADJUST CARPET SHIM AT ENTRANCED TO BATH TOO HIGH AND CARPET RAISED AT RIGHT CORNER OF WINDOW**



**152123 - 3 - FLOORING~ADJUST CARPET SHIM AT ENTRANCED TO BATH TOO HIGH AND CARPET RAISED AT RIGHT CORNER OF WINDOW**



**152123 - 4 - FLOORING~ADJUST CARPET SHIM AT ENTRANCED TO BATH TOO HIGH AND CARPET RAISED AT RIGHT CORNER OF WINDOW**



**it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**