

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W161172 Pack Slip:202021

Service Date: Dec 13, 2022

Priority:	Normal		Status:	SCHEDULED		RELEASED
BUILDER						
Customer:	N000508		City:	WHITBY	Received:	Jun 03, 2022
Name:	ZANCOR WHITBY	′	Service Phone(s	):	Time:	
Service Fax:			Site Phone:	,	Order:	D374317-1
Site Fax:			Lot#:	BLK 3 - 19	Phase:	PH1
RESIDENT	INFORMATION					
Home Owner	r Name: SARVATH	IANAN JEGATHEES	AN Addres	s: 16 LAKI	E TRAIL WAY	
Home Phone	e(s): 647-213-0	970	Work P	hone(s):		
Cell Phone(s	):		Email(s	s): vathana	n.jegatheesan@gmai a@gmail.com	l.com,
LINKED OF	RDER INFORMATI	ON (D374317-1)				
	N000508 ZANCOR			Lot #: BL	K 3 - 19	
Model:	TH-2			Phase: Ph		
SERVICE IN	NSTRUCTIONS					
REPLACE THE HANDLE	HE FRONT DOOR S E ON SITE	LAB ON LINE: 91 (EI	NT). PLEASE INCLU	DE ALL MULTI-POI	INT GUTS IN THE SL	AB AND SWAP
	DROOM-WINDOWS	-ADJUST PATIO DO	OR			
PARTS REC						
LN Item Desc		Location	Specification	Size	Options	Qty
PLEASE GUTS II HANDLI	LAD DOOR SYS E INCLUDE ALL MUI N THE SLAB AND S' E ON SITE po 78062 OR LIGHT SELECTE	WAP THE	SLABS (ALL)	37.25 X 97.75	LEFT MENNIE FLI WOODGRAIN WO FERCO_MULTIPO	USH 1 88F MP
Problem Desc	cription:	P				
Warranty				RGEABLES		
Material \$			Materia			
Labour \$			Labour	\$ 1		
Cause:		Note for b	P.O.#:			
Solution:	* Builder	todo p	oilly bock	slela X		
Date Comp	eleted: Dec 13	2022	App	proved: J. Jul		
	Time:		Service Sig	nature:	ALEX	



## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W161172 Pack Slip:202021

Service Date: Dec 13, 2022

Model: TH-2  SERVICE INSTRUCTIONS  REPLACE THE FRONT DOOR SLAB ON LINE: 91 (ENT). PLEASE INCLUDE ALL MULTI-POINT GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE  ADD:  MASTER BEDROOM-WINDOWS-ADJUST PATIO DOOR  PARTS REQUIRED  LN Item Description Location Specification Size Options Qty 91 2' 10" CLAD DOOR SYS ENT SLABS (ALL) 37.25 X 97.75 LEFT MENNIE FLUSH 1 PLEASE INCLUDE ALL MULTI-POINT WOODGRAIN WG8F MP FERCO_MULTIPOINT BK HANDLE ON SITE po 78062									
Customer: N000508	Priority:	Normal		Status:	SCHED	JLED			RELEASED
Name: ZANCOR WHITBY	BUILDER								
Service Fax:	Customer:	N000508		City:	WHITBY	•	Recei	ved:	Jun 03, 2022
Site Fax:	Name:	ZANCOR WHITBY		Service Phone(s):			Time:	:	
RESIDENT INFORMATION	Service Fax:			Site Phone:			Order	r:	D374317-1
Home Owner Name:   SARVATHANAN JEGATHEESAN   Address:   16 LAKE TRAIL WAY	Site Fax:			Lot#:	BLK 3 -	19	Phase	e:	PH1
Home Phone(s): 647-213-0970	RESIDENT	INFORMATION							
Home Phone(s): 647-213-0970	Home Owne	r Name: SARVATHANAN JEG	ATHEESAN	Address:		16 LAKE	TRAIL WAY		
Email(s):   vathanan,jegatheesan@gmail.com,   jegafam@gmail.com				Work Pho					
jegafam@gmail.com   jega		, ,			` '	vathanar	n.iegatheesan@	බamail.c	com.
Customer: N000508 ZANCOR WHITBY	·	,		(-).				99	,
Model: TH-2	LINKED OF	RDER INFORMATION (D374	1317-1)						
SERVICE INSTRUCTIONS  REPLACE THE FRONT DOOR SLAB ON LINE: 91 (ENT). PLEASE INCLUDE ALL MULTI-POINT GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE  ADD:  MASTER BEDROOM-WINDOWS-ADJUST PATIO DOOR  PARTS REQUIRED  LN Item Description 91 2' 10" CLAD DOOR SYS ENT SLABS (ALL) 37.25 x 97.75 LEFT MENNIE FLUSH 1 PLEASE INCLUDE ALL MULTI-POINT GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE po 78062 92 NO DOOR LIGHT SELECTED ENT 1  Problem Description:  Warranty Material \$ CHARGEABLES MATERIAL CHARGEABLES	Customer:	N000508 ZANCOR WHITBY			Lot #:	BL	< 3 - 19		
REPLACE THE FRONT DOOR SLAB ON LINE: 91 (ENT). PLEASE INCLUDE ALL MULTI-POINT GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE  ADD: MASTER BEDROOM-WINDOWS-ADJUST PATIO DOOR  PARTS REQUIRED  LIN Item Description Location Specification Size Options Qty 91 2' 10" CLAD DOOR SYS ENT SLABS (ALL) 37.25 X 97.75 LEFT MENNIE FLUSH 1 WOODGRAIN WG8F MP FERCO_MULTIPOINT WOODGRAIN WG8F MP FERCO_MULTIPOINT BK  HANDLE ON SITE po 78062 92 NO DOOR LIGHT SELECTED ENT 1  Problem Description:  Warranty Material \$ Labour \$ P.O.#:  Cause:  Date Completed:  Approved:  Time: Service Signature:	Model:	TH-2			Phase	: PH	1		
THE HANDLE ON SITE  ADD:  MASTER BEDROOM-WINDOWS-ADJUST PATIO DOOR  PARTS REQUIRED  Location Specification Size Options Qty 91 2' 10" CLAD DOOR SYS ENT SLABS (ALL) 37.25 X 97.75 LEFT MENNIE FLUSH 1 PLEASE INCLUDE ALL MULTI-POINT GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE po 78062  92 NO DOOR LIGHT SELECTED ENT 1  Problem Description:  Warranty CHARGEABLES Material \$ Labour \$ P.O.#:  Cause:  Date Completed: Approved:	SERVICE II	NSTRUCTIONS							
THE HANDLE ON SITE  ADD:  MASTER BEDROOM-WINDOWS-ADJUST PATIO DOOR  PARTS REQUIRED  Location Specification Size Options Qty 91 2' 10" CLAD DOOR SYS ENT SLABS (ALL) 37.25 X 97.75 LEFT MENNIE FLUSH 1 PLEASE INCLUDE ALL MULTI-POINT GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE po 78062  92 NO DOOR LIGHT SELECTED ENT 1  Problem Description:  Warranty CHARGEABLES Material \$ Labour \$ P.O.#:  Cause:  Date Completed: Approved:			NE: 91 (ENT	). PLEASE INCLUD	E ALL MU	LTI-POIN	NT GUTS IN T	HE SLA	B AND SWAP
MASTER BEDROOM-WINDOWS-ADJUST PATIO DOOR  PARTS REQUIRED  Location Specification Size Options Qty 91 2' 10" CLAD DOOR SYS ENT SLABS (ALL) 37.25 X 97.75 LEFT MENNIE FLUSH PLEASE INCLUDE ALL MULTI-POINT GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE po 78062 92 NO DOOR LIGHT SELECTED ENT 1  Problem Description:  Warranty Material \$ Labour	THE HANDL	E ON SITE							
MASTER BEDROOM-WINDOWS-ADJUST PATIO DOOR  PARTS REQUIRED  Location Specification Size Options Qty 91 2' 10" CLAD DOOR SYS ENT SLABS (ALL) 37.25 X 97.75 LEFT MENNIE FLUSH PLEASE INCLUDE ALL MULTI-POINT GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE po 78062 92 NO DOOR LIGHT SELECTED ENT 1  Problem Description:  Warranty Material \$ Labour	ADD.								
PARTS REQUIRED  LN Item Description   Location   Specification   Size   Options   Qty   91 2' 10" CLAD DOOR SYS   ENT   SLABS (ALL)   37.25 X 97.75   LEFT MENNIE FLUSH   WOODGRAIN WG8F MP   PLEASE INCLUDE ALL MULTI-POINT   GUTS IN THE SLAB AND SWAP THE   HANDLE ON SITE po 78062   92 NO DOOR LIGHT SELECTED   ENT   1  Problem Description:    Warranty   CHARGEABLES   Material \$ Labour \$ P.O.#:    Cause:   Labour \$ P.O.#:    Date Completed:   Approved:   Approved:   Approved:   CHARGEABLES     Service Signature:   Service Signature:   CHARGEABLES     Cause:	11	DROOM-WINDOWS-AD ILIST F							
LN Item Description 91 2' 10" CLAD DOOR SYS PLEASE INCLUDE ALL MULTI-POINT GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE po 78062 92 NO DOOR LIGHT SELECTED  Warranty Material \$ Labour \$ Labour \$ P.O.#:  Date Completed:  Date Completed:  Specification Size Options Qty Specification Size Options Size Options Qty WOODGRAIN WG8F MP FERCO_MULTIPOINT BK  1  CHARGEABLES Material \$ Labour \$ P.O.#:  Cause:  Date Completed:  Approved:  Time: Service Signature:			ATIO DOOI	`					
91 2' 10" CLAD DOOR SYS PLEASE INCLUDE ALL MULTI-POINT GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE po 78062  92 NO DOOR LIGHT SELECTED ENT 1  Problem Description:    Warranty			Location	Specification	Cino		Ontions		06
PLEASE INCLUDE ALL MULTI-POINT GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE po 78062  92 NO DOOR LIGHT SELECTED ENT 1  Problem Description:						( 97 75	-	JIE ELLIS	
GUTS IN THE SLAB AND SWAP THE HANDLE ON SITE po 78062  92 NO DOOR LIGHT SELECTED ENT 1  Problem Description:			LIVI	OLABO (ALL)	37.237	(91.15			
92 NO DOOR LIGHT SELECTED ENT 1  Problem Description:    Warranty									
Problem Description:		·							
Problem Description:	92 NO DO	OR LIGHT SELECTED	ENT						1
Warranty	8 _	9 1							
Material \$	Problem Des	cription:							
Material \$	☐ Warranty			Псил	OCEARLE				
Labour \$         P.O.#:           Cause:         P.O.#:    Approved:  Time:  Service Signature:									
P.O.#:  Cause:  Solution:  Date Completed:  Time:  Service Signature:		-							
Cause:	Labour \$				-				
Solution:	0								
Solution:	Cause:								
Solution:									
Date Completed:									
Date Completed:									
Time: Service Signature:									
Time: Service Signature:									
Time: Service Signature:ALEX	Date Comp	oleted:		Appr	roved:				
Time: Service Signature: ALEX									
Time: Service Signature: ALEX									
ALEX		Time:		Service Sign	ature:				
					-				



Normal

Priority:

## NEWMAR WINDOW MFG, INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

Status:

FILL

ON ORDER

WO # W161172 Pack Slip:202021

RELEASED

Service Date: Oct 11, 2022

BUILDER									
Customer: N	1000508			City:	WHITBY		Received:	Jun 03, 20	22
Name: Z	ANCOR	WHITBY		Service Phone(s):	8		Time:		
Service Fax:				Site Phone:			Order:	D374317-	·1
Site Fax:				Lot#:	BLK 3 - 19	9	Phase:	PH1	
RESIDENT INF	FORMA	TION							
Home Owner Na	ame: S/	ARVATHANAN JEG	SATHEESAN	Address	: 16	6 LAKE	TRAIL WAY		
Home Phone(s):	64	7-213-0970		Work Ph	none(s):				
Cell Phone(s):				Email(s)			jegatheesan@gmai gmail.com	l.com,	
LINKED ORDE	ER INFO	RMATION (D374	317-1)						
Customer: N0	00508 Z	ANCOR WHITBY			Lot #:	BLK	3 - 19		
Model: TH	l <b>-</b> 2				Phase:	PH1			
SERVICE INST	TRUCTI	ONS							
REPLACE THE I		DOOR SLAB ON LI	NE: 91 (ENT)	). PLEASE INCLUI	DE ALL MUL	TI-POIN	T GUTS IN THE SL	AB AND SW	AP
ADD: MASTER BEDRO	OOM-WI	NDOWS-ADJUST I	PATIO DOOF	₹			+/U		
PARTS REQU	IRED								
LN Item Descript	ion		Location	Specification	Size		Options		Qty
GUTS IN T HANDLE O	NCLUDE THE SLAE DN SITE (	ALL MULTI-POINT B AND SWAP THE DO 78062		SLABS (ALL)	37.25 X	97.75	LEFT MENNIE FL WOODGRAIN WG FERCO_MULTIPO	SSF MP	1
92 NO DOOR	LIGHT S	SELECTED	ENT						1
Problem Descrip	itlon:		11-11-	***					
Warranty				Псна	RGEABLES				
J Material \$				Material					
_abour \$		≂ = a		Labour	\$				
		( NO Acc	e0 ( )	P.O.#:					
Cause:		( / 0 1100			. 1		0		
	1-1	O NOT	Honre	I Cal	1/01	he	said 1	Ne ane	
- la	1-	17	1				<u> </u>		_
Solution:	40 1	Home To	ter) ()	Re BOOK	-)				
			_						
Date Complete	ed: _ <i>Q</i> (	T11-2	012	Apı	proved:	***			_
Tim	ne;			Service Sig	ınature;		ZAHER		
							Edt		
									_

ZANCOR Zancor Homes (Parkview) Ltd. Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closing	Data	08Sep22
Closina	Date.	ODSCHEE

Address:

Location:

Now Towns In Brooklin - Phase: 1 - Lot: Unit 19 (Block 3)

Today's Date:

27Sep22

Contact(s):

Sarvathanan Jegatheesan - Cell: (647) 213-0970 -

(vathanan.jegatheesan@gmail.com)

Subramaniam Jegatheesan - (jegafam@gmail.com) Thirumalar Jegatheesan - (jegafam@gmail.com)

Email:

vathanan.jegatheesan@gmail.com

Company: Newmar

Attention:

Alex

Telephone:

(905) 672-1233

Fax:

(905) 672-6350

Please Complete the following items:

DAI	Туре	Issue	Appt. Date/Time	Notes
150354	PDI	MASTER BEDROOM- WINDOWS~ADJUST PATIO DOOR		

Date Completed: Dec 13 2022

Homeowner Signature: The Homeowner acknowledges and accepts all work

has been completed in a workman like manner.

Date Completed: 200/13/2022

Trade &/or Service Tech.

Signature:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

## Now Towns In Brooklin - Phase: 1 - Lot: Unit 19 (Block 3)

150354 - 1 - WINDOWS~ADJUST PATIO DOOR

