



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W169536
Pack Slip:222228

Service Date: Jan 02, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000531 City: CALEDON Received: Oct 14, 2022
Name: ZANCOR CALEDON CLUB Service Phone(s): Time:
Service Fax: Site Phone: Order: D385442-1
Site Fax: Lot#: BLK149-2 Phase:

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D385442-1)

Customer: N000531 ZANCOR CALEDON CLUB Lot #: BLK149-2
Model: RLTH-02 HIGHLAND (CB) Phase:

SERVICE INSTRUCTIONS

BED 3 AND BED2 WINDOW ARM DAMAGED

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
132	NEWMAR VINYL CASEMENT ROTO GEAR	B3	OTHER RPLCMNT PARTS	30 X 60	CB 61316 FJ RIGHT	1
141	NEWMAR VINYL CASEMENT ROTO GEAR	B2	OTHER RPLCMNT PARTS	30 X 60	CB 61316 FJ LEFT	1

Problem Description: no body on site to sign

☐ Warranty

Material \$ _____

Labour \$ _____

☐ CHARGEABLES

Material \$ NIC

Labour \$ _____

P.O.#:

Cause: _____

Solution: Changed (3) Rotorgears

Date Completed: Jan 02/23

Approved: _____

Time: 3:00pm

Service Signature: [Signature]

STEVE



Service Department <servicedept@newmar.com>

Zancor Homes- Caledon- BLK 149 unit 2

1 message

Beata Slipska <Beata@zancorhomes.com>

Fri, Oct 7, 2022 at 1:41 PM

To: Shonnessa Facey <sfacey@newmar.com>, "servicedept@newmar.com" <servicedept@newmar.com>

Good Afternoon,

Please schedule for service
Unit 2 bedroom 3 and bedroom 2
Damaged arm. Thank you



10/14/22, 9:54 AM

Newmar / Casa Bella Mail - Zancor Homes- Caledon- BLK 149 unit 2



Kind Regards,
Bea

416-566-5475