



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W167868
Pack Slip:202608

Service Date: Jan 03, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000508 City: WHITBY Received: Sep 20, 2022
Name: ZANCOR WHITBY Service Phone(s): Time: AM
Service Fax: Site Phone: Order: D374335-1
Site Fax: Lot#: BLK 6 - 37 Phase: PH1

RESIDENT INFORMATION

Home Owner Name: ZAIB, UN, NISA GILANI Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): 416-662-4766 Email(s): zaibgilani@hotmail.com

LINKED ORDER INFORMATION (D374335-1)

Customer: N000508 ZANCOR WHITBY Lot #: BLK 6 - 37
Model: TH-2 Phase: PH1

SERVICE INSTRUCTIONS

EXTERIOR PORCH-WHITE MARKS / SCRATCHES RIGHT SIDE TRIM AT FRONT DOOR

FOYER/HALLNOTE:-ADJUST FRONT DOOR

Complete

**WE HAVE A LOCK BOX AT THE PROPERTY LOCATED AT THE GARAGE DOOR
THE LOCK BOX # IS 1956

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
90	DOOR JOIN 2 PART vinyl cladding	ENT	OTHER RPLCMNT PARTS	52.5 X 97.75	BK 61316 FJ	1

Problem Description: tenant signed Backing

☐ Warranty

☐ CHARGEABLES

Material \$ _____

Material \$ NIC

Labour \$ _____

Labour \$ _____

P.O.#:

Cause: _____

Solution: Adjusted Front Door - touch up Vinyl Joints

Date Completed: Jan 03/23

Approved: _____

Time: 1 1/2 hr

Service Signature: _____

STEVE



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W167868
Pack Slip: 202608
Service Date: Oct 05, 2022

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: N000508
Name: ZANCOR WHITBY
Service Fax:
Site Fax:

City: WHITBY
Service Phone(s):
Site Phone:
Lot#: BLK 6 - 37

Received: Sep 20, 2022
Time:
Order: D374335-1
Phase: PH1

RESIDENT INFORMATION

Home Owner Name: ZAIB, UN, NISA GILANI
Home Phone(s):
Cell Phone(s): 416-662-4766

Address:
Work Phone(s):
Email(s): zaibgilani@hotmail.com

LINKED ORDER INFORMATION (D374335-1)

Customer: N000508 ZANCOR WHITBY
Model: TH-2

Lot #: BLK 6 - 37
Phase: PH1

SERVICE INSTRUCTIONS

EXTERIOR PORCH-WHITE MARKS / SCRATCHES RIGHT SIDE TRIM AT FRONT DOOR

FOYER/HALLNOTE:-ADJUST FRONT DOOR

**WE HAVE A LOCK BOX AT THE PROPERTY LOCATED AT THE GARAGE DOOR
THE LOCK BOX # IS 1956

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
90	DOOR JOIN 2 PART vinyl cladding	ENT	OTHER RPLCMNT PARTS	52.5 X 97.75	BK 61316 FJ	1

Problem Description:

No time

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

MANNY



Zancor Homes (Parkview) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 25Aug22

Address:

Location: Now Towns In Brooklin - Phase: 1 - Lot: Unit 37 (Block 6)

Today's Date: 25Aug22

Contact(s): Zaib, Un, Nisa Gilani - Cell: (416) 662-4766 - (zaibgilani@hotmail.com)

Email: zaibgilani@hotmail.com

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
149673	PDI	EXTERIOR- PORCH~WHITE MARKS / SCRATCHES RIGHT SIDE TRIM AT FRONT DOOR			
149677	PDI	FOYER/HALL- NOTE:~ADJUST FRONT DOOR			

Date Completed: _____

Homeowner Signature: 

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: Jan 03/23

Trade &/or Service Tech.

Signature: 

Print Name: Steven Maia

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and

it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Now Towns In Brooklin - Phase: 1 - Lot: Unit 37 (Block 6)

**149673 - 1 - PORCH-WHITE MARKS / SCRATCHES
RIGHT SIDE TRIM AT FRONT DOOR**

