

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD MISSISSAUGA ON L4T 4G6

WO # W169127 Pack Slip:202605

Service Date: Jan 03 2023

| newmar | | | | | 05) 672-1233 FAX | K (905) 672-1076 | 400 | | Serv | nce Date. | Jai | 1 03, 2023 |
|---------------------|-------------|----------------------------|---------|---------|------------------|----------------------|---------|----------|-----------------|------------------------------------|--------|-------------|
| Priority: | Normal | | | | Status: | | SCHED | ULED | | | R | ELEASED |
| BUILDER | | | | | | | | | | | | |
| Customer: | N00050 | 3 | | | City: | | WHITBY | , | | Received: | 0 | ct 07, 2022 |
| Name: | ZANCO | R WHITBY | | | Service F | Phone(s): | | | | Time: | | |
| Service Fax: | | | | | Site Pho | ne: | | | | Order: | D | 374332-1 |
| Site Fax: | | | | | Lot#: | | BLK 6 - | 34 | | Phase: | PI | H1 |
| RESIDENT | INFORM | ATION | | | | | | | | | | |
| Home Owner | Name: | THURSHIGA H | KANTHAF | RUPEN | | Address: | | 32 LAKE | TRAIL | WAY | | |
| Home Phone | e(s): | | | | | Work Phor | ne(s): | | | | | |
| Cell Phone(s |): | 416-262-8969 | | | | Email(s): | | kantharu | pen@g | mail.com, Th | usi42 | 7@gmail.con |
| LINKED OF | RDER INF | ORMATION | (D37433 | 32-1) | | | | | | | | |
| Customer: | N000508 | ZANCOR WHI | TBY | | | | Lot #: | BL | (6 - 34 | Call H | o if | late/n |
| Model: | TH-3 / IN | ΓEND | | | | | Phase | | | home | for | lock be |
| SERVICE IN | NSTRUC' | TIONS | | | | | | | | code. | | |
| KNOW IF TH | IIS IS A TE | OWS-CRACK (EMPERED GLA | ASS | | | | | S ORDE | RED PI | LEASE MR V | VILL N | NEED TO |
| | | DING DOOR S | CREEN N | OT WOF | RKING AT I | REAR BALO | CONY | (| e hi | por | e | |
| PARTS REC | | | | | | | | | | r | | |
| LN Item Desc | • | IDOLL DATIO | | ocation | Specifica | | Size | V 00 07 | Option | | | Qt |
| COMPL | | JRCH. PATIO | DOOR F | REC | | NS-REPLA IT-DOORS | | X 92.37 | BUC | 1316 RIGHT KINGHAM PI O DOOR | JRCH | i. |
| 110 BUCKIN COMPL | | JRCH. PATIO | DOOR E | SKF | | NS-REPLA IT-DOORS | | X 92.37 | BUC | 1316 LEFT KINGHAM PI O DOOR | JRCH | i. |
| 205 NEWMA COMPL | | CASEMENT | Ε | 33 | GLASS SASH | ONLY - | 18.75 > | 〈 46.75 | AG13 BK | BK/WH LO | NE_A | RG 1 |
| 336 NEWMA | AR VINYL | CASEMENT | N | 1.ENS | GLASS SASH | ONLY - | 18.75 〉 | 〈 46.75 | AG13 BK | BK/WH LO | NE_A | IRG 1 |
| Problem Desc | cription: | 90f | Loc | k Ba | od Co | nde | H/c | no | f L | rue | | |
| Warranty | | | | | | CHARG | EABLES | 3 | | | | |
| Material \$ | - | | | | | Material \$ | 20 | 4 | | | | |
| _abour \$ | | | | | | Labour \$ | 13 | 200 | | | | |
| | | | | | | P.O.#: | 71 | 40 | | | | |
| Cause: | | | | | | | | * | | | | |
| Solution: | | | | | | | | , | | | | П |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| Date Comp | leted: | Jan o | 3/2 | 3 | | Appro | ved: | | _ | 7 | | |



NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W169127

Pack Slip:202605

Service Date: Nov 25, 2022

| Priority: | Normal | | Status: | SCHEDULED | | RELEASED |
|----------------|---|-----------|-------------------------------|----------------|--|-----------------|
| BUILDER | | | | | | |
| Customer: | N000508 | | City: | WHITBY | Received | Oct 07, 2022 |
| Name; | ZANCOR WHITBY | | Service Phone(s): | | Time: | |
| Service Fax: | | | Site Phone: | | Order: | D374332-1 |
| Site Fax: | | | Lot#: | BLK 6 - 34 | Phase: | PH1 |
| RESIDENT I | NFORMATION | | | | | |
| Home Owner | Name: THURSHIGA KANTHA | RUPEN | Address: | 32 LAKE 7 | TRAIL WAY | |
| Home Phone(s | s): | | Work Phor | ne(s): | | |
| Cell Phone(s): | 416-262-8969 | | Email(s): | kantharup | en@gmail.com, Thus | si427@gmail.com |
| LINKED OR | DER INFORMATION (D374) | 332-1) | | | // |) |
| Customer: 1 | N000508 ZANCOR WHITBY | | | Lot #: BLK | 6 - 34 | |
| Model: | TH-3 / INT END | | | Phase: PH1 | 116 | / |
| SERVICE IN | STRUCTIONS | | | | 1 1 | |
| | 3 - WINDOWS-CRACK ON RIG S IS A TEMPERED GLASS | HT OPERAT | ING WINDOWIF N | IO PARTS ORDER | ED PLEASE MR WII | LL NEED TO |
| EVTERIORNIC | OTE:-SLIDING DOOR SCREEN | NOT WORK | INIC AT DEAD DAL | CONV. | ODA Lee | |
| PARTS REQ | | NOT WORK | | place | Usen Lee | K- 808 |
| LN Item Descr | ription | Location | Specification | Size | Options | Qty |
| 100 BUCKING | GHAM PURCH. PATIO DOOR | REC | SCREENS-REPLA CEMENT-DOORS | | BK 61316 RIGHT BUCKINGHAM PUP PATIO DOOR | RCH. |
| 110 BUCKING | GHAM PURCH. PATIO DOOR | BKF | SCREENS-REPLA CEMENT-DOORS | | BK 61316 LEFT BUCKINGHAM PUP PATIO DOOR | RCH. |
| 205 NEWMAR | R VINYL CASEMENT | B3 | GLASS ONLY - SASH | 18.75 X 46.75 | AG13 BK/WH LOW BK | E_ARG 1 |
| Problem Descr | ription: Was 91 | ven in | Pary Si | Le Poru | plant C | 1834 85034) |
| Warranty | 7.17 | | CHARG | SEABLES | | |
| Material \$ | | | Material \$ | | | |
| _abour\$ | | | Labour \$ | | | |
| Cause: | tenen | - Mar | P.O.#: | shano erea | V Nov | 26 |
| Solution: | need () | 183/4 | x 4634 A6 | -13 Black | | |
| Date Comple | eted: Nov 25/ | 22 | Appro | ved: | | |
| Т | ime: <u>3ouan</u> | -10 | Service Signa | ture: | | |



Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

| Now T | owns in Brooklin - Phase: 1 - Lo | ot: Unit 34 (Block 6 |) |
|----------------------------|---|---|--|
| Alex (905) 6 (905) 6 | 72-1233 72-6350 | | |
| Туре | Issue | Appt. Date/Time | Notes |
| PDI | BEDROOM #3- WINDOWS~CRACK ON RIGHT OPERATING WINDOW | | |
| PDI | EXTERIOR- NOTE:~SLIDING DOOR SCREEN NOT WORKING AT REAR BALCONY | | |
| | Newmon Alex (905) 6 (905) 6 Type | Newmar Alex (905) 672-1233 (905) 672-6350 lete the following items: Type BEDROOM #3- WINDOWS~CRACK ON RIGHT OPERATING WINDOW PDI EXTERIOR- NOTE:~SLIDING DOOR SCREEN NOT WORKING AT REAR | Newmar Alex (905) 672-1233 (905) 672-6350 lete the following items: Type Issue Appt. Date/Time PDI BEDROOM #3- WINDOWS~CRACK ON RIGHT OPERATING WINDOW PDI EXTERIOR- NOTE:~SLIDING DOOR SCREEN NOT WORKING AT REAR |

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Now Towns In Brooklin - Phase: 1 - Lot: Unit 34 (Block 6)

150710 - 1 - WINDOWS~CRACK ON RIGHT OPERATING WINDOW



150716 - 1 - NOTE:~SLIDING DOOR SCREEN NOT WORKING AT REAR BALCONY

