Enrollment:

Purchaser Name: Nirmal K Nijjar

Phone Res: (647) 283-1655 Phone Bus: (416) 987-3435 Closing Date: February 02, 2023 Inspector: Gisella Fiore

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 144A / 1 Plan:

Address: Municiaplity:

Inspection Date: January 25, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
TRIM	LARGE DAMAGE AT TRIM OF OPERATING WINDOW TO BE REPLACED	
MASTER BEDROOM		
WALLS	BLACK MARK AT STIPPLE CEILING	
SHARED ENSUITE		
VANITY CABINETS	INSPECT MARKS AT 3RD BANK OF DRAWER	
TRIM	HO REQUESTING FOR SMALL BASEBOARD RIGHT OF TUB WALL TILE AT FLOOR LINE TO BE REMOVED	
BEDROOM #4		
WINDOWS	DAMAGE AT ASTRICAL MIDDLE	
WALLS	LINE IN STIPPLE WHERE WALL AND CATHEDRAL CEILING MEET RIGHT AND LEFT SIDE	
BEDROOM 4 ENSUITE		
FLOORING	HOLES IN TILE IN SHOWER	
VANITY CABINETS	CHIP AT BOTTOM GABLE BELOW LEFT SINK	
FOYER/HALL		
STAIRS	DENT ON 2ND TREAD AT STAIRS FROM 2ND LANDING TO 2ND FLOOR 2) REMOVED STABLE AT 2ND TREAD AT STAIRS FROM 2ND LANDING TO 2ND FLOOR 3) FILL GAPS AT 1ST TREAD AND LANDING TO 2ND LANDING TO 2ND FLOOR AND AT FIRST TREAD AT MAIN FLOOR TO FIRST LANDING	
	SECURE TRIM LEFT OF NOSING AT 2ND LANDING TO 2ND FLOOR	
FRONT DOORS	CHIPS AT MIDDLE ASTRICAL	
	PAIN DRIPS ON FRONT DOOR INTERIOR	
KITCHEN		
CABINETS	RAISE UPPER CORNER CABINET RIGHT OF FRIDGE 2) SCRATCH ON UPPER CORNER CABINET RIGHT OF FRIDGE GABLE INSIDE SAND UPPER RIGHT DOOR RIGHT OF FRIDGE 3) FILL NAIL HOLES THROUGHOUT AT CROWN MOULDING 4) LARGE SEAM VISIBLE AT CROWN MOULDING LEFT OF HOOD FAN 5) CHIP ON UPPER LEFT CABINET LEFT OF PANTRY 6) ADJUST DRAWERS RIGHT OF FRIDGE ADJUST GARBAGE DRAWER LEFT OF PANTY	
	RIGHT AND LEFT PANTRY DOORS CHIPPED BOTTOM	
ELECTRICAL/LIGHTING	15 AMP REQUIRED FOR MICROWAVE	

Enrollment:

Purchaser Name: Nirmal K Nijjar

Phone Res: (647) 283-1655
Phone Bus: (416) 987-3435
Closing Date: February 02, 2023
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 144A / 1

Plan: Address: Municiaplity:

Inspection Date: January 25, 2023

Page 2 of 2

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS. To designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASI	
I have inspected my new home and	I agree that the description of the items listed	on this form are accurate.	
Nirmal K Nijjar	New Non		
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Gisella Fiore	Mh
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/01/25	January 25, 2023	