

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W172614 Pack Slip:210678

Service Date: Jan 13, 2023

| Priority: | Normal | | Status | SCHEDULE | D | RELEASED |
|-----------------------|---------------------------------------|------------|-----------------------|------------|--|--|
| BUILDER | | | | | | |
| Customer: | N000531 | | City: | CALEDON | Receive | ed: Nov 18, 2022 |
| Name: | ZANCOR CALEDON CLUB | | Service Phone(s): | | Time: | |
| Service Fax: | | | Site Phone: | | Order: | D380142-1 |
| Site Fax: | | | Lot#: | 57A | Phase: | |
| RESIDENT | INFORMATION | | | | | |
| Home Owner | Name: | | Address: | CAL DRI | EDON CLUB - PHA | SE: 1 / 6 CALABRIA |
| Home Phone(| (s): | | Work Pho | ne(s): | | |
| Cell Phone(s) | 647-267-9521 | | Email(s): | | abhay@gmail.com, ana.bafana@gmail.c | com |
| LINKED OR | DER INFORMATION (D380 | 142-1) | | | | |
| Customer: | N000531 ZANCOR CALEDON | CLUB | | Lot #: | 57A | |
| Model: | 30-05 CAPILANO (STND + OP | T. GROUND) | (BK) | Phase: | | |
| SERVICE IN | ISTRUCTIONS | | | ^ | | |
| LIVING ROOM | M- WINDOWS-CIRCLE CRACK | ON LEFT FI | XED WINDOW | do | | |
| | | | | | Ω | Committee to the Control of the Cont |
| 152299 - BED PORCH | DROOM #4- WINDOWS-SCRAT | TCH ON UPP | ER RIGHT FIXED (| BLASS ABOV | E OPERATING AT | SED ROOM ABOVE |
| 152307 - MAS | STER BEDROOM- WINDOWS- | SMALL CHIP | AT UPPER LEFT (| ORNER FIXE | ED WINDOW | in HETURAL |
| | STER ENSUITE BATH- WALLS | | | | | Conam |
| | | | 20m | OTTLLED = | - MR. 30 | ×42 |
| 152315 - FOY | 'ER/HALL- FRONT DOORS-AD | DJUST 👩 | Low | | | |
| PARTS REC | QUIRED | | | | | |
| LN Item Desc | • | Location | Specification | Size | Options | Qty |
| 21 NEWMA crack on | R VINYL CASEMENT FIXED glass | DIN/FAM | GLASS ONLY - FIXED | 18.75 X 62 | 75 CLR LOWE_/ | ARG BK 1 |
| | R VINYL PICTURE WINDOW CH ON GLASS | B3 | GLASS ONLY - FIXED | 21.875 X 1 | 5.875 CLR'LOWE_A | ARG BK 1 |
| | | | | | | |
| Problem Desc | cription: | | | | | |
| Warranty | | | ☐ CHAR | GEABLES | | |
| | | | Material \$ | | | |
| Labour \$ | | | Labour \$ | ing | | |
| Labour ϕ | | | P.O.#: | 740 | | |
| Cause: | == | | | 61 | | |
| | | | | | | |
| Solution: | | | | | | |
| | | | | | | |
| Data Carrel | latad | | Λ | wod. | | |
| Date Compl | leted: | | Appro | .veu | | |

| Time: | Service Signature; | | |
|-------|--------------------|-----|--|
| | | BVA | |





ZANCOR Zancor Homes (Caledon) Ltd. Warranty Services

Phone: (905) 738-7010 Fax: (905) 738-5948

Closing Date: 25Nov22

Address:

Location:

Caledon Club - Phase: 1 - Lot: 57A

Today's Date:

Contact(s): Email:

Company:

Newmar

17Nov22

Attention:

Alex

Telephone:

(905) 672-1233

Fax:

(905) 672-6350

Please Complete the following items:

| DAI | Туре | Issue | Appt. Date/Time | Notes |
|--------|------|---|--------------------|-------|
| 152290 | PDI | LIVING ROOM- WINDOWS~CIRCLE CRACK ON LEFT FIXED WINDOW | | |
| 152299 | PDI | BEDROOM #4- WINDOWS~SCRATC H ON UPPER RIGHT FIXED GLASS ABOVE OPERATING AT BED ROOM ABOVE PORCH | | |
| 152307 | PDI | MASTER BEDROOM- WINDOWS~SMALL CHIP AT UPPER LEFT CORNER FIXED WINDOW | | |
| 152312 | PDI | MASTER ENSUITE BATH- WALLS~SCREEN ON WINDOW NOT INSTALLED | | MR |
| 152315 | PDI | FOYER/HALL- FRONT DOORS~ADJUST | | |

| | | OPERATING DOOR | | | | |
|---|--------|----------------|----------|--------------|----------------------|--------|
| Date Completed: 13/01/2023 Homeowner Signature: | | | | | re: 31- | |
| | | / / | | | nowledges and accep | |
| | | / / | nas bee | en completed | in a workman like ma | inner. |
| Date Comple | eted:(| 3/01/23 | Trade 8 | k/or Service | Tech. | |
| | | | Signatu | re: | | 020 |
| | | | Print Na | ıme: | REY | |

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Caledon Club - Phase: 1 - Lot: 57A

152290 - 1 - WINDOWS~CIRCLE CRACK ON LEFT FIXED WINDOW



152307 - 1 - WINDOWS~SMALL CHIP AT UPPER



152315 - 1 - FRONT DOORS~ADJUST OPERATING DOOR



152299 - 1 - WINDOWS~SCRATCH ON UPPER RIGHT FIXED GLASS ABOVE OPERATING AT BED ROOM ABOVE PORCH



152312 - 1 - WALLS~SCREEN ON WINDOW NOT INSTALLED

