



Zancor Homes (Parkview) Ltd.

Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closing Date: 12Oct22

Address:

Location: Now Towns In Brooklyn - Phase: 1 - Lot: Unit 34 (Block 6)

Today's Date: 05Oct22

Contact(s):

Email:

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
150710	PDI	BEDROOM #3- WINDOWS~CRACK ON RIGHT OPERATING WINDOW		
150716	PDI	EXTERIOR- NOTE:~SLIDING DOOR SCREEN NOT WORKING AT REAR BALCONY		

Date Completed:

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed:

Trade &/or Service Tech.

Signature:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W169127
Pack Slip:202605
Service Date: Nov 25, 2022

Priority: Normal

BUILDER

Customer: N000508

Name: ZANCOR WHITBY

Service Fax:

Site Fax:

Status:

SCHEDULED

RELEASED

City: WHITBY

Received: Oct 07, 2022

Service Phone(s):

Time:

Site Phone:

Order: D374332-1

Lot#:

BLK 6 - 34

PH1

RESIDENT INFORMATION

Home Owner Name: THURSHIGA KANTHARUPEN

Address: 32 LAKE TRAIL WAY

Home Phone(s):

Work Phone(s):

Cell Phone(s): 416-262-8969

Email(s): kantharupen@gmail.com, Thusi427@gmail.com

LINKED ORDER INFORMATION (D374332-1)

Customer: N000508 ZANCOR WHITBY

Lot #: BLK 6 - 34

Model: TH-3 / INT END

Phase: PH1

SERVICE INSTRUCTIONS

BEDROOM #3 - WINDOWS-CRACK ON RIGHT OPERATING WINDOW-IF NO PARTS ORDERED PLEASE MR WILL NEED TO KNOW IF THIS IS A TEMPERED GLASS

EXTERIORNOTE:-SLIDING DOOR SCREEN NOT WORKING AT REAR BALCONY

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
100	BUCKINGHAM PURCH. PATIO DOOR REC	REC	SCREENS-REPLA CEMENT-DOORS	35.375 X 92.375	BK 6'13'16 RIGHT BUCKINGHAM PURCH. PATIO DOOR	1
110	BUCKINGHAM PURCH. PATIO DOOR BKF	BKF	SCREENS-REPLA CEMENT-DOORS	35.375 X 92.375	BK 6'13'16 LEFT BUCKINGHAM PURCH. PATIO DOOR	1
205	NEWMAR VINYL CASEMENT	B3	GLASS ONLY - SASH	18.75 X 46.75	AG13 BKWH LOWE_ARG BK	1

Problem Description:

was given wrong size from plant (18'34 x 50'34)
need AG13

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$

Labour \$

Labour \$

P.O.#:

Cause:

tenant move in tomorrow Nov 26

Solution:

need 1 18'34 x 46'34 AG13 Black

Date Completed:

Nov 25/22

Approved:

-

Time:

3:00pm

Service Signature:

[Signature]



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W169127
Pack Slip:202605
Service Date: Jan 03, 2023

Priority:	Normal	Status:	SCHEDULED	RELEASED	
BUILDER					
Customer:	N000508	City:	WHITBY	Received:	Oct 07, 2022
Name:	ZANCOR WHITBY	Service Phone(s):		Time:	
Service Fax:		Site Phone:		Order:	D374332-1
Site Fax:		Lot#:	BLK 6 - 34	Phase:	PH1

RESIDENT INFORMATION

Home Owner Name:	THURSHIGA KANTHARUPEN	Address:	32 LAKE TRAIL WAY
Home Phone(s):		Work Phone(s):	
Cell Phone(s):	416-262-8969	Email(s):	kantharupen@gmail.com, Thusi427@gmail.com

LINKED ORDER INFORMATION (D374332-1)

Customer:	N000508 ZANCOR WHITBY
Model:	TH-3 / INT END

Lot #: BLK 6 - 34
Phase: PH1

Call up if late/not home for lock box code.

SERVICE INSTRUCTIONS

BEDROOM #3 - WINDOWS-CRACK ON RIGHT OPERATING WINDOW--IF NO PARTS ORDERED PLEASE MR WILL NEED TO KNOW IF THIS IS A TEMPERED GLASS

EXTERIORNOTE:-SLIDING DOOR SCREEN NOT WORKING AT REAR BALCONY

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
100	BUCKINGHAM PURCH. PATIO DOOR	REC	SCREENS-REPLA CEMENT-DOORS	35.375 X 92.375	BK 61316 RIGHT BUCKINGHAM PURCH. PATIO DOOR	1
110	BUCKINGHAM PURCH. PATIO DOOR	BKF	SCREENS-REPLA CEMENT-DOORS	35.375 X 92.375	BK 61316 LEFT BUCKINGHAM PURCH. PATIO DOOR	1
205	NEWMAR VINYL CASEMENT	B3	GLASS ONLY - SASH	18.75 X 46.75	AG13 BK/WH LOWE_ARG BK	1
336	NEWMAR VINYL CASEMENT	M.ENS	GLASS ONLY - SASH	18.75 X 46.75	AG13 BK/WH LOWE_ARG BK	1

Complete

Problem Description: got Lock Box Code H/o not drive

☐ Warranty	☐ CHARGEABLES
Material \$	Material \$ <u>204</u>
Labour \$	Labour \$ <u>190</u>
	P.O.#: <u>240</u>

Cause:	
Solution:	

Date Completed: Jan 03/23
Shonnessa

Approved: [Signature]