

ZANCOR

HOMES

Zancor Homes (Parkview) Ltd.

Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closing Date: 17Oct22

Address:

Location: Now Towns In Brooklyn - Phase: 1 - Lot: Unit 40 (Block 7)

Today's Date: 05Oct22

Contact(s):

Email:

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
150697	PDI	FOYER/HALL-WINDOWS-CRACKED FIX GLASS LEFT OF OPERATING WINDOW			
150700	PDI	BEDROOM #3-WINDOWS-MULLIN DAMAGED ABOVE OPERATING WINDOW			
150702	PDI	MASTER BEDROOM-WINDOWS-SCREENS MISSING THROUGHOUT HOME			

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____

Print Name: _____



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 872-1233 FAX (905) 872-1076

WO # W169280
Pack Slip:215753
Service Date: Jan 06, 2023

Priority: Normal
BUILDER
Customer: N000508
Name: ZANCOR WHITBY
Service Fax:
Site Fax:

Status: SCHEDULED RELEASED
City: WHITBY
Service Phone(s):
Site Phone:
Lot#: BLK 7 - 40
Received: Oct 11, 2022
Time: AM
Order: D374338-1
Phase: PH1

RESIDENT INFORMATION

Home Owner Name: YUMEI FANG & ROBERT L MARANGE Address: 27 LAKE TRAIL WAY
Home Phone(s): 416-562-8689, 613-294-7512 Work Phone(s):
Cell Phone(s): Email(s): yumeifang@rogers.com,
rmaranger@gmail.com

LINKED ORDER INFORMATION (D374338-1)

Customer: N000508 ZANCOR WHITBY Lot #: BLK 7 - 40
Model: TH-2 Phase: PH1

SERVICE INSTRUCTIONS

-BEDROOM #3-WINDOWS-MULLIN DAMAGED ABOVE OPERATING WINDOW

-MASTER BEDROOM- WINDOWS-SCREENS MISSING THROUGHOUT HOME - Done

- FOYER / HALL WINDOWS - CRANKED FIXED GLASS LEFT OF OPERATING WINDOW - couldn't find Broken Glass

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
116	NEWMAR VINYL CASEMENT FIXED	LIV	GLASS ONLY - FIXED	24.75 X 56.75	CLR LOWE_ARG BK	1
120	M12 MULTI JOIN	B3	OTHER RPLCMNT PARTS	78 X 70	BK 61316 FJ	1
170	BUCKINGHAM PURCH. PATIO DOOR MB	MB	SCREENS-REPLA CEMENT-DOORS	35.375 X 78.375	BK 61316 RIGHT BUCKINGHAM PURCH. PATIO DOOR	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

rent didn't want us to go in master bedroom



Shonnessa Facey <sfacey@newmar.com>

Zancor whitby blk7-40
2 messages

Tue, Oct 4, 2022 at 1:42 PM

Louie Tesoro <tesorotruck13@gmail.com>
To: Newmar <service@newmar.com>
Cc: Ted <tschlosser@newmar.com>, Tesoro <tesorowindows@bellnet.ca>
RR/rec-14 window glass broken on fixed panel 78x80 H/L



20221004_130143.jpg
2138K

Tue, Oct 4, 2022 at 2:31 PM

Melissa Green <mgreen@newmar.com>
To: Shonnessa Facey <sfacey@newmar.com>

please input

[Quoted text hidden]

We are making some changes to better serve you. Effective immediately all new service requests are to be sent to servicedept@newmar.com if enquiring about a follow up please email me directly at mgreen@newmar.com

Thank you 🙏

Melissa Green
Customer Service Coordinator

20221004_130143.jpg
2138K