Enrollment:

Purchaser Name: Jayeshkumar Kal Patel

Pushpabahenn Jay Patel

Phone Res:

Phone Bus: (416) 716-6825 Closing Date: March 09, 2023 HOMES

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 23A / 1 Plan:

Address: Municiaplity:

Inspection Date: February 13, 2023

Inspector: Gisella Fiore Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

FOYER/HALL		
FLOORING	DENT ON FIRST PLANK BY NOISING AT STAIRS FROM MAIN FLOOR TO 2ND FLOOR AT FIRST	
	LANDING	
STAIRS	CRACK BELOW NOSING AT FIRST LANDING AT STAIRS TO 2ND FLOOR AT RISER	
MASTER ENSUITE BATH		
NOTE:	TILE NOT INSTALLED INSIDE SHOWER	
VANITY CABINETS	BLACK MARK ON CABINET BELOW SINK	
MASTER BEDROOM		
WALLS	BLACK MARKS AT STIPPLE CEILING IN CLOSET	
MAIN BATHROOM		
COUNTERTOPS	CRACK AT SIDE SPLASH LEFT OF SINK	
EXTERIOR		
NOTE:	SOFFIT AT FRONT PORCH CEILING WHERE ELECTRICAL PLUG WAS INSTALLED DENTED	
PAINT	EXTERIOR PAINTING NOT COMPLETE	
DINING ROOM		
WINDOWS	DINNING ROOM WINDOW TO BE ADJUSTED	
KITCHEN		
CABINETS	DAMAGE BACK GABLE AT UPPER CABINET LEFT OF FRIDGE	
	SCRATCH AT UPPER LEFT CABINET RIGHT OF HOODFAN	
	CHIP AT BOTTOM LEFT CABINET BELOW SINK AT ISLAND	
	CRACK INSIDE UPPER GABLE AT UPPER LEFT CABINET LEFT OF HOODFAN	
	CHIP AT BOTTOM LEFT CABINET LEFT OF FRIDGE AT CORNER AND DOOR SCRATCHED	
	MISSING SHELF LEFT CABINET RIGHT OF FRIDGE	
	CHIPS AT RIGHT GABLE RIGHT OF SINK AT ISLAND	

Enrollment:

Purchaser Name: Jayeshkumar Kal Patel

Pushpabahenn Jay Patel

Phone Res:

Phone Bus: (416) 716-6825 Closing Date: March 09, 2023 Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Purchaser's Signature

Inspector's Signature

Lot / Phase: 23A / 1 Plan:

Address: Municiaplity:

Inspection Date: February 13, 2023

LIVING ROOM		
WALLS	INSPECT PAINT AT TRIM ARCH WAY AT ENTRANCE TO LIVING ROM FROM KITCHEN RIGHT SIDE	
BASEMENT		
COLD ROOM	ADJUST WEATHER STRIP AT COLD CELLAR ROOM	
NOTE:	AS PER HOMEOWNER INSPECT CRACK IN CONCRETE AT DRAIN FOR TOLERANCE	

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

Purchaser's Name (print)

Inspector's Name (print)

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

RIWER

Purchaser's Name (print)

Designate's Name (print)

Jayeshkumar Kal Patel Pushpabahenn Jay Patel

Purchaser's Signature

Gisella Fiore

Designate's Signature Date (YYYY/MM/DD) 2023/02/13 February 13, 2023