



Zancor Homes (Innisfil) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 20Oct22

Address:

Location: Belle Aire Shores - Phase: 3 - Lot: 186W

Today's Date: 10Jan23

Contact(s): Pankaj Bassi - Cell: (705) 493-1387 - (pankajbassi@gmail.com)
Sarka Bassi

Email: pankajbassi@gmail.com

Company: River Valley Masonry Group LTD

Attention: Carlos - Cell: 416-991-3009

Telephone: (905) 270-0599

Fax: (905) 270-0256

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
151278	PDI	EXTERIOR- NOTE:~CRACKED BRICK AT UPPER LEFT SIDE OF HOME LEFT OF WINDOW ABOVE GARAGE 2) CHIP ON TWO BRICKS LEFT SIDE OF HOUSE ABOVE EAVESTROUGH AND GAS 3) FIVE BRICKS CHIPPED RIGHT OF FIREPLACE ON EXTERIOR LEFT SIDE OF HOUSE 4) LARGE CHIPPED BRICK LEFT SIDE OF HOUSE LEFT OF FIREPLACE 5) INSPECT CHIPS ON BRICKS ON RIGHT SIDE OF HOUSE.		

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____ Trade &/or Service Tech.

Signature: _____

Print Name: Carlos

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

151278 - 1 - NOTE:~CRACKED BRICK AT UPPER LEFT SIDE OF HOME LEFT OF WINDOW ABOVE GARAGE 2) CHIP ON TWO BRICKS LEFT SIDE OF HOUSE ABOVE EAVESTROUGH AND GAS 3) FIVE BRICKS CHIPPED RIGHT OF FIREPLACE ON EXTERIOR LEFT SIDE OF HOUSE 4) LARGE CHIPPED BRICK LEFT SIDE OF HOUSE LEFT OF FIREPLACE 5) INSPECT CHIPS ON BRICKS ON RIGHT SIDE OF HOUSE.



151278 - 2 - NOTE:~CRACKED BRICK AT UPPER LEFT SIDE OF HOME LEFT OF WINDOW ABOVE GARAGE 2) CHIP ON TWO BRICKS LEFT SIDE OF HOUSE ABOVE EAVESTROUGH AND GAS 3) FIVE BRICKS CHIPPED RIGHT OF FIREPLACE ON EXTERIOR LEFT SIDE OF HOUSE 4) LARGE CHIPPED BRICK LEFT SIDE OF HOUSE LEFT OF FIREPLACE 5) INSPECT CHIPS ON BRICKS ON RIGHT SIDE OF HOUSE.



151278 - 3 - NOTE:~CRACKED BRICK AT UPPER LEFT SIDE OF HOME LEFT OF WINDOW ABOVE GARAGE 2) CHIP ON TWO BRICKS LEFT SIDE OF HOUSE ABOVE EAVESTROUGH AND GAS 3) FIVE BRICKS CHIPPED RIGHT OF FIREPLACE ON EXTERIOR LEFT SIDE OF HOUSE 4) LARGE CHIPPED BRICK LEFT SIDE OF HOUSE LEFT OF FIREPLACE 5) INSPECT CHIPS ON BRICKS ON RIGHT SIDE OF HOUSE.



151278 - 4 - NOTE:~CRACKED BRICK AT UPPER LEFT SIDE OF HOME LEFT OF WINDOW ABOVE GARAGE 2) CHIP ON TWO BRICKS LEFT SIDE OF HOUSE ABOVE EAVESTROUGH AND GAS 3) FIVE BRICKS CHIPPED RIGHT OF FIREPLACE ON EXTERIOR LEFT SIDE OF HOUSE 4) LARGE CHIPPED BRICK LEFT SIDE OF HOUSE LEFT OF FIREPLACE 5) INSPECT CHIPS ON BRICKS ON RIGHT SIDE OF HOUSE.



151278 - 5 - NOTE:~CRACKED BRICK AT UPPER LEFT SIDE OF HOME LEFT OF WINDOW ABOVE GARAGE 2) CHIP ON TWO BRICKS LEFT SIDE OF HOUSE ABOVE EAVESTROUGH AND GAS 3) FIVE BRICKS CHIPPED RIGHT OF FIREPLACE ON

EXTERIOR LEFT SIDE OF HOUSE 4) LARGE
CHIPPED BRICK LEFT SIDE OF HOUSE LEFT OF
FIREPLACE 5) INSPECT CHIPS ON BRICKS ON
RIGHT SIDE OF HOUSE.

