



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W173410
Pack Slip:219021

Service Date: Mar 01, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Nov 30, 2022
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time: AM
Service Fax: Site Phone: Order: D380367-1
Site Fax: Lot#: 38W Phase: 3

RESIDENT INFORMATION

Home Owner Name: ZHANJIANG LIU/ PING PAN Address: N/A
Home Phone(s): Work Phone(s):
Cell Phone(s): 647-857-5657 Email(s): cherrypan25@hotmail.com

LINKED ORDER INFORMATION (D380367-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 38W
Model: 42-06 MASTHEAD/WH Phase: 3

SERVICE INSTRUCTIONS

OUTSTANDING

LIVING ROOM-WINDOWS-CRACK AT UPPER LEFT FIXED WINDOW--NEED LONG LADDER

**NEED LONG LADDER PLEASE MAKE SURE WE HAVE ON THE DAY OF SERVICE **

THIS IS A MUST DO

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
190	DCGH 2' 8" WOOD DOOR SYS LOCK SIDE JAMB COMPLETED	G/H	OTHER RPLCMNT PARTS	33.75 X 81.75	61316 FJ LEFT DCGH 2' 8" WOOD DOOR SYS	1
191	NO DOOR LIGHT SELECTED	G/H				1
312	NEWMAR VINYL CASEMENT FIXED COMPLETED	MB	GLASS ONLY - FIXED	24.75 X 42.75	CLR LOWE_ARG WH	1
322	NEWMAR VINYL CASEMENT FIXED	OTB	GLASS ONLY - FIXED	24.75 X 42.75	CLR LOWE_ARG WH	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ 190

Labour \$ 120

P.O.#:

Cause: Replaced broken glass complete

Solution:

Date Completed: Feb-Mar 01, 23

Approved: [Signature]

Time: _____

Service Signature: _____


THARMA





NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

FM

WO # W173410

Pack Slip: 219021

Service Date: Feb 08, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Nov 30, 2022
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time: AM
Service Fax: Site Phone: Order: D380367-1
Site Fax: Lot#: 38W Phase: 3

RESIDENT INFORMATION

Home Owner Name: N/A Address: N/A
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D380367-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 38W
Model: 42-06 MASTHEAD/WH Phase: 3

SERVICE INSTRUCTIONS

G/H-190 JAMB DAMAGED LOCK SIDE H/L

- Complete

ADD:

MASTER BEDROOM- WINDOWS-CRACK ON LEFT FIXED WINDOW LEFT OF OPERATING
LIVING ROOM-WINDOWS-CRACK AT UPPER LEFT FIXED WINDOW

- Complete

- 2 men

Long Ladder
at Least 28' Feet

THIS IS A MUST DO

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
190	DCGH 2' 8" WOOD DOOR SYS LOCK SIDE JAMB	G/H	OTHER RPLCMNT PARTS	33.75 X 81.75	61316 FJ LEFT DCGH 2' 8" WOOD DOOR SYS	1
191	NO DOOR LIGHT SELECTED	G/H				1
312	NEWMAR VINYL CASEMENT FIXED	MB	GLASS ONLY - FIXED	24.75 X 42.75	CLR LOWE_ARG WH	1
322	NEWMAR VINYL CASEMENT FIXED	OTB	GLASS ONLY - FIXED	24.75 X 42.75	CLR LOWE_ARG WH	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Feb 08/23

Approved:

30 min



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7530 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1070

WO # W173410
Pack Slip: 219021

Service Date: Jan 02, 2023

Priority: Normal Status: SCHEDULED RELEASED
BUILDER
Customer: 611313 City: INNISFIL Received: Nov 30, 2022
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D380367-1
Site Fax: Lot#: 38W Phase: 3

RESIDENT INFORMATION

Home Owner Name: N/A Address: N/A
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D380367-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 38W
Model: 42-06 MASTHEAD/WH Phase: 3

SERVICE INSTRUCTIONS

G/H-190 JAMB DAMAGED LOCK SIDE H/L

ADD:

MASTER BEDROOM- WINDOWS-CRACK ON LEFT FIXED WINDOW LEFT OF OPERATING
LIVING ROOM-WINDOWS-CRACK AT UPPER LEFT FIXED WINDOW

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
190	DCGH 2' 8" WOOD DOOR SYS LOCK SIDE JAMB	G/H	OTHER RPLCMNT PARTS	33.75 X 81.75	61316 FJ LEFT DCGH 2' 8" WOOD DOOR SYS	1
191	NO DOOR LIGHT SELECTED	G/H				1
312	NEWMAR VINYL CASEMENT FIXED	MB	GLASS ONLY - FIXED	24.75 X 42.75	CLR LOWE ARG WH	1
322	NEWMAR VINYL CASEMENT FIXED	OTB	GLASS ONLY - FIXED	24.75 X 42.75	CLR LOWE ARG WH	1

Problem Description: House occupied / NOT ACCESS leave door TAG (11:30 AM)

☐ Warranty

☐ CHARGEABLES

Material \$ _____

Material \$ _____

Labour \$ _____

Labour \$ _____

P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____ Approved: _____

Time: _____ Service Signature: _____



Zancor Homes (Innisfil) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 19Aug21

Address:

Location: Belle Aire Shores - Phase: 3 - Lot: 38W

Today's Date: 08Dec22

Contact(s): Zhanjiang Liu - Home: (647) 857-5657 - (cherrypan25@hotmail.com)
Ping Pan - (Cherrypan@hotmail.com)

Email: cherrypan25@hotmail.com

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
152893	PDI	MASTER BEDROOM- WINDOWS~CRACK ON LEFT FIXED WINDOW LEFT OF OPERATING			
152899	PDI	LIVING ROOM- WINDOWS~CRACK AT UPPER LEFT FIXED WINDOW			

Date Completed: _____

Homeowner Signature: X Zhanjiang
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: mar. 01. 23

Trade &/or Service Tech:

Signature: Pharm

Print Name: Pharm

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Belle Aire Shores - Phase: 3 - Lot: 38W

**152893 - 1 - WINDOWS~CRACK ON LEFT FIXED
WINDOW LEFT OF OPERATING**



**152899 - 1 - WINDOWS~CRACK AT UPPER LEFT
FIXED WINDOW**

