



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W175884  
Pack Slip: 214898

Service Date: Mar 17, 2023

Priority: Normal Status: SCHEDULED RELEASED  
BUILDER  
Customer: N000531 City: CALEDON Received: Jan 11, 2023  
Name: ZANCOR CALEDON CLUB Service Phone(s): Time:  
Service Fax: Site Phone: Order: D383567-1  
Site Fax: Lot#: 142A Phase:

RESIDENT INFORMATION

Home Owner Name: PARDEEP GOEL/ GUPTA SAKASHI Address: 146 PETCH AVE  
Home Phone(s): Work Phone(s):  
Cell Phone(s): 647-786-5394, 647-786-9728 Email(s): goel.pardeep@gmail.com, guptasakshit@gmail.com

LINKED ORDER INFORMATION (D383567-1)

Customer: N000531 ZANCOR CALEDON CLUB  
Model: 38-05 GLENDALE (RR UPG)/LOT 142A (SL)

Lot #: 142A  
Phase:

SERVICE INSTRUCTIONS

NOTE:-DAMAGE ON TRIM ABOVE OPERATING DOOR AT EXTERIOR LEFT SIDE  
DINING ROOM-WINDOWS-SCRATCH ON RIGHT FIXED GLASS RIGHT OF OPERATING WINDOW  
BEDROOM #4- WINDOWS-CHIP ON WINDOW CRANK AT OPERATING WINDOW  
KITCHEN- WINDOWS-BUBBLE ON LEFT MULLIN LEFT OF DOOR AT TRIM

PARTS REQUIRED

| LN  | Item Description                    | Location | Specification       | Size          | Options                              | Qty |
|-----|-------------------------------------|----------|---------------------|---------------|--------------------------------------|-----|
| 31  | NEWMAR VINYL CASEMENT FIXED         | DIN      | GLASS ONLY - FIXED  | 18.75 X 54.75 | CLR LOWE ARG SL                      | 1   |
| 120 | NEWMAR VINYL CASEMENT crank chipped | B4       | OTHER RPLCMNT PARTS | 24 X 48       | SL 61316 FJ LEFT                     | 1   |
| 151 | 5' 8" CLAD DOOR SYS trim damage     | ENT      | OTHER RPLCMNT PARTS | 72 X 97.75    | SL 61316 FJ LEFT 5' 8" CLAD DOOR SYS | 1   |
| 152 | E130_STYLE DOORLITE                 | ENT      | OTHER RPLCMNT PARTS | 20 X 80       | E130_STYLE DOORLITE                  | 2   |

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ 45

Labour \$ 120

P.O.#:

Cause:

Solution: REPLACEMENT OF GLASS

Date Completed: MAR 17 2022

Approved:

Time: \_\_\_\_\_

Service Signature: \_\_\_\_\_

RAY



**Zancor Homes (Caledon) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 26Jan23

**Address:**

**Location:** Caledon Club - Phase: 1 - Lot: 142A

**Today's Date:** 10Jan23

**Contact(s):**

**Email:**





**Company:** Newmar

**Attention:** Alex

**Telephone:** (905) 672-1233

**Fax:** (905) 672-6350

**Please Complete the following items:**


| DAI    | Type | Issue   |  | Appt.<br>Date/Time | Notes   |
|--------|------|---|--|--------------------|---|
| 153794 | PDI  | EXTERIOR-<br>NOTE:~DAMAGE ON<br>TRIM ABOVE<br>OPERATING DOOR<br>AT EXTERIOR LEFT<br>SIDE    |  |                    |  |
| 153623 | PDI  | DINING ROOM-<br>WINDOWS~SCRATC<br>H ON RIGHT FIXED<br>GLASS RIGHT OF<br>OPERATING<br>WINDOW |  |                    |  |
| 153632 | PDI  | BEDROOM #4-<br>WINDOWS~CHIP ON<br>WINDOW CRANK AT<br>OPERATING<br>WINDOW                    |  |                    |  |
| 153639 | PDI  | KITCHEN-<br>WINDOWS~BUBBLE<br>ON LEFT MULLIN<br>LEFT OF DOOR AT<br>TRIM                     |  |                    |  |

**Date Completed:**

Mar 17 / 2023

**Homeowner Signature:**

The Homeowner acknowledges and accepts all work



has been completed in a workman like manner.

Date Completed: MARCH 12, 2023

Trade &/or Service Tech.

Signature: 

Print Name: PEY

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

**Caledon Club - Phase: 1 - Lot: 142A**

**153794 - 1 - NOTE:~DAMAGE ON TRIM ABOVE  
OPERATING DOOR AT EXTERIOR LEFT SIDE**




**153623 - 1 - WINDOWS~SCRATCH ON RIGHT  
FIXED GLASS RIGHT OF OPERATING WINDOW**



**153623 - 2 - WINDOWS~SCRATCH ON RIGHT  
FIXED GLASS RIGHT OF OPERATING WINDOW**



**153632 - 1 - WINDOWS~CHIP ON WINDOW CRANK  
AT OPERATING WINDOW**



**153639 - 1 - WINDOWS~BUBBLE ON LEFT  
MULLIN LEFT OF DOOR AT TRIM**



**153639 - 2 - WINDOWS~BUBBLE ON LEFT  
MULLIN LEFT OF DOOR AT TRIM**

