



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 25Nov22

Address:

Location: Caledon Club - Phase: 1 - Lot: 57A

Today's Date: 17Nov22

Contact(s):

Email:

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
152290	PDI	LIVING ROOM- WINDOWS-CIRCLE CRACK ON LEFT FIXED WINDOW		✓
152299	PDI	BEDROOM #4- WINDOWS~SCRATC H ON UPPER RIGHT FIXED GLASS ABOVE OPERATING AT BED ROOM ABOVE PORCH		✓
152307	PDI	MASTER BEDROOM- WINDOWS~SMALL CHIP AT UPPER LEFT CORNER FIXED WINDOW		✓
152312	PDI	MASTER ENSUITE BATH- WALLS~SCREEN ON WINDOW NOT INSTALLED		MR
152315	PDI	FOYER/HALL- FRONT DOORS~ADJUST		✓

	OPERATING DOOR			
--	----------------	--	--	--

Date Completed: 12/01/2023

Homeowner Signature: [Signature]
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: 12/01/23

Trade &/or Service Tech.

Signature: [Signature]

Print Name: REY

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G8
TEL (905) 672-1233 FAX (905) 672-1076

WO # W172614
Pack Slip:210678
Service Date: Feb 13, 2023

Priority:	Normal	Status:	SCHEDULED
BUILDER			
Customer:	N000531	City:	CALEDON
Name:	ZANCOR CALEDON CLUB	Service Phone(s):	
Service Fax:		Site Phone:	
Site Fax:		Lot#:	57A
Received:	Nov 18, 2022	Time:	
Order:	D380142-1	Phase:	

RESIDENT INFORMATION

Home Owner Name:	Address:	CALEDON CLUB - PHASE: 1 / 6 CALABRIA DRI	
Home Phone(s):	Work Phone(s):		
Cell Phone(s):	Email(s):	fineabhay@gmail.com, chetana.bafana@gmail.com	

LINKED ORDER INFORMATION (D380142-1)

Customer:	N000531 ZANCOR CALEDON CLUB	Lot #:	57A
Model:	30-05 CAPILANO (STND + OPT. GROUND) (BK)	Phase:	

SERVICE INSTRUCTIONS

- LIVING ROOM- WINDOWS-CIRCLE CRACK ON LEFT FIXED WINDOW
- 152299 - BEDROOM #4- WINDOWS-SCRATCH ON UPPER RIGHT FIXED GLASS ABOVE OPERATING AT BED ROOM ABOVE PORCH
- 152307 - MASTER BEDROOM- WINDOWS-SMALL CHIP AT UPPER LEFT CORNER FIXED WINDOW
- 152312 - MASTER ENSUITE BATH- WALLS-SCREEN ON WINDOW NOT INSTALLED
- 152315 - FOYER/HALL- FRONT DOORS-ADJUST

ADD:

MAIN HALL - WINDOW IS NOT PROPERLY SQUARE
FOYER - SCREW COVER IS MISSING (INTERIOR)

Completed

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
21	NEWMAR VINYL CASEMENT FIXED crack on glass COMPLETED	DIN/FAM	GLASS ONLY - FIXED	18.75 X 62.75	CLR LOWE_ARG BK	1
143	NEWMAR VINYL PICTURE WINDOW SCRATCH ON GLASS COMPLETED	B3	GLASS ONLY - FIXED	21.875 X 15.875	CLR LOWE_ARG BK	1
221	NEWMAR VINYL CASEMENT	ENS	SCREENS-REPLA CEMENT-WINDO WS	25.0625 X 43.125		1

Problem Description:

No signed Backup

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

176
120

Cause: _____


Solution: _____

Date Completed: Feb 13/23

Approved: _____

Time: 1:45 pm

Service Signature: _____



STEVE