Enrollment:

Purchaser Name:

Gagandeep Kaur Bhullar

Phone Res:

Phone Bus: (647) 702-8900 Closing Date: June 19, 2023 Inspector: Gisella Fiore

HOMES

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 149 Unit 4 / 1

Plan: Address: Municiaplity:

Page 1 of 2 Inspection Date: March 24, 2023 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

FOYER/HALL		•	•
STAIRS	VARNISH REQUIRED AT NOSING AT LANDING TO 3RD FLOOR AND INSIDE AND OUTSIDE STRINGER AT STAIRS TO 3RD FLOOR		
	WATER DAMAGE ON NOSING AT SECOND-FLOOR AND NEWEL POST AND RISER AND TREAD		
	CHIP ON OUTSIDE STRINGER AT STAIRS FROM LANDING TO MAIN FLOOR 2) CHIP AND SCRATCH ON SUPPORT BEAM AT STAIRS TO 1ST FLOOR FROM MAIN		
	CHIPS ON THE RAILING WHERE IT MEETS SUPPORT POST AT LANDING TO FIRST FLOOR		
	SLOPPY TRIM AT CORNER FROM MAIN FLOOR TO FIRST LANDING TO 2ND FLOOR		
	EXPOSED SCREW AT LANDING FROM FIRST FLOOR TO SECOND FLOOR BELOW NOSING 2)		
	CRACKED STRINGER RIGHT OF NOSING AT STAIRS FROM FIRST FLOOR TO FIRST LANDING TO		
	SECOND FLOOR 3) CRACKED STRINGER AT 8TH TREED AT STAIRS FROM MAIN FLOOR TO 2ND FLOOR		
MASTER ENSUITE BATH			
VANITY CABINETS	CHIP AT BOTTOM GABLE BELOW SINK		
COUNTERTOPS	INSPECT SCRATCH RIGHT OF SINK		
NOTE:	GAPS AND CRACKED GROUT AT WALL TILE BY FAUCETS		
MASTER BEDROOM			
TRIM	DAMAGED ASTRICAL		
KITCHEN			
CABINETS			
LAUNDRY ROOM			
NOTE:	SHIFT ON BOTTOM RIGHT GABLE BELOW SINK		
POWDER ROOM			
NOTE:	FIRST FLOOR FLOOR POWDER ROOM CHIPS AT LEFT AND RIGHT DOOR		
EXTERIOR			
PAINT	NOT COMPLETE		

Enrollment:
Purchaser Name: ?????

Gagandeep Kaur Bhullar

Phone Res:

Phone Bus: (647) 702-8900
Closing Date: June 19, 2023
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 149 Unit 4 / 1

Plan: Address: Municiaplity:

Inspection Date: March 24, 2023

Page 2 of 2

A REFERENCE FOR FUTURE WARRAN	TY REQUESTS. signate someone to conduct the PDI in the	HOME'S CONDITION BEFORE THE PURCHASES in place should ensure they provide written author				
I have inspected my new home and I agree that the description of the items listed on this form are accurate.						
?????	Gene	Gagandeep Kaur Bhullar				
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature			
		Gisella Fiore				
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature			
Date (YYYY/MM/DD)	2023/03/24	March 24, 2023				