



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W182171

Pack Slip:221982

Service Date: Mar 30, 2023

Priority: Normal

Status: PENDING

BUILDER

Customer: N000531

City: CALEDON

Received: Mar 29, 2023

Name: ZANCOR CALEDON CLUB

Service Phone(s):

Time:

Service Fax:

Site Phone:

Order: D386555-1

Site Fax:

Lot#: 23B

Phase:

RESIDENT INFORMATION

Home Owner Name:

Address:

Home Phone(s):

Work Phone(s):

Cell Phone(s):

Email(s):

LINKED ORDER INFORMATION (D386555-1)

Customer: N000531 ZANCOR CALEDON CLUB

Lot #: 23B

Model: 30-06 WESTMOUNT (SL)

Phase:

SERVICE INSTRUCTIONS

BED 2 WINDOW IS MISSING TRACK (WINDOW CANNOT OPEN OR CLOSE) *done*

BED 3 WINDOW - ARM KEEPS COMING OFF THE TRACK *done*

DEN - WINDOW WILL NOT CLOSE *done*

PATIO DOOR - WILL NOT LOCK *done*

** THIS LOT SHOULD BE OPEN IF LOCK SEE BUILDER **

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
271	NEWMAR VINYL CASEMENT roto gear	B3	OTHER RPLCMNT PARTS	30 X 68	SL 61316 FJ RIGHT <i>#38</i>	1
381	NEWMAR VINYL CASEMENT maxim hardware pivot (small black piece) hinge track	B2	OTHER RPLCMNT PARTS	30 X 68	SL 61316 FJ LEFT <i>N/C</i>	1

Problem Description:

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$ *38*

Labour \$

Labour \$ *120*

P.O.#:

Cause:

Solution:

Date Completed: *Mar 30-2023*

Approved: *X* *[Signature]*

Time:

Service Signature: *[Signature]*

ZAHER

[Signature]



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W182171

Pack Slip:221982

Service Date: Mar 30, 2023

Priority: Normal Status: PENDING

BUILDER

Customer: N000531 City: CALEDON Received: Mar 29, 2023
Name: ZANCOR CALEDON CLUB Service Phone(s):
Service Fax: Site Phone: Order: D386555-1
Site Fax: Lot#: 23B Phase:

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D386555-1)

Customer: N000531 ZANCOR CALEDON CLUB Lot #: 23B
Model: 30-06 WESTMOUNT (SL) Phase:

SERVICE INSTRUCTIONS

BED 2 WINDOW IS MISSING TRACK (WINDOW CANNOT OPEN OR CLOSE)
BED 3 WINDOW - ARM KEEPS COMING OFF THE TRACK
DEN - WINDOW WILL NOT CLOSE
PATIO DOOR - WILL NOT LOCK

** THIS LOT SHOULD BE OPEN IF LOCK SEE BUILDER **

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
271	NEWMAR VINYL CASEMENT roto gear	B3	OTHER RPLCMNT PARTS	30 X 68	SL 61316 FJ RIGHT	1
381	NEWMAR VINYL CASEMENT maxim hardware pivot (small black piece) hinge track	B2	OTHER RPLCMNT PARTS	30 X 68	SL 61316 FJ LEFT	1

Problem Description: _____

☐ Warranty

Material \$ _____

Labour \$ _____

☐ CHARGEABLES

Material \$ _____

Labour \$ _____

P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

ZAHAR



Christina Pellegrini <cpellegrini@newmar.com>

D386555 / N000531 ZANCOR CALEDON CLUB / Lot 23B

1 message

Mathew Harant <mharant@newmar.com>

Wed, Mar 29, 2023 at 8:08 AM

To: Christina Pellegrini <cpellegrini@newmar.com>

Cc: Michael Koopmans <mkoopmans@newmar.com>

Hi Christina,

Can you please create a SWO for the following items (please ask service if these issues can be addressed ASAP):

Bed 2 window is missing track (window cannot open or close)

Bed 3 window - arm keeps coming off the track

Den - Window will not close

Patio door - Will not lock

Hi Mike,

Lock up service was completed for this lot on January 26th. These issues should be completed at lock up service right?

Thank you,

--
Mathew Harant
Sales Account Manager

Newmar Window Manufacturing Inc.

7630 Airport Road

Mississauga, Ontario L4T 4G6

Tel: 905-672-1233

Fax: 905-672-1076

Toll Free: 1-800-263-5634

www.newmar.com

Click here for information on Newmar Aluminum Window Wall systems

Manufacturers of Quality Windows and Entrance Door Systems

Please consider the environment before printing this email.

This e-mail and any attachments may contain information that is privileged and/or confidential. If you are not the intended recipient and appear to have received this e-mail in error, please notify us immediately and then delete all copies from your computer system. Any unauthorized use, copying or further distribution is prohibited. Please also note that if you send us e-mails containing time-sensitive or important instructions, you should ensure that receipt has been timely acknowledged in view of the potential for misdirection or inadvertent interception. Thank you.



