



IN-SERVICE Work Order

WO No: W-206573

WO Date: 03/13/2023

Contractor: RYAN WALL

Builder : ASPEN RIDGE HOMES

Project : R-ASP520 - ASPEN RIDGE-SEATON

Address : 2482 FLORENTINE PLACE

City : PICKERING

Contact :

Phone :

Cell:

Lot No: 065

Model: CASH FB2

Block:

Phase:

Name:

Closing:

PDI Date:

Sch'd Date

Start Date

Comp Date

Unit Model

Serial No

04/03/2023

EL196UH070XE36B

5920G09900

QTY

MATERIAL & WORK REQUIRED

SERIAL NO

Airflow Readings

Behind couch 43

Bedroom 1 47

Bedroom 2 19

All BSMR.

New Airflow Readings

Behind couch 62

Bedroom 1 64

Bedroom 2 52

— BSMR Airflow was comparable to main floor Airflow. Increased system pressure for better Airflow throughout.

* Furniture can't be left in front / on top of Registers.

WO Notes :

** Please arrive 8-12

Booked with builder

Check 2 bedroom and 1 register in living room behind couch registers minimal air flow.

Contractor

Invoice No

Invoice Amt

Date

Site Super Sign

Supplier: NATIONAL AIR SYSTEMS INC. 10 FARNBORO RD. Etobicoke, ON M9W 0A1 Phone: (416)532-0654	Work At: LAS LOMAS DEVELOPMENT INC. Dharmakulaseelan, Bavithra 2482 FLORENTINE PLACE Pickering, ON	Contact: Dharmakulaseelan, B avithra Home Ph: Bus. Ph: Cell. Ph: (416)697-6040 tmayuresan@gmail.com
---	---	--

Work Order: 2120, 00001179

Project: LAS LOMAS DEVELOPMENT INC.	WO Type: 1 Year List	Priority: Scheduled
Lot: 065	Work Status: In Process	Last Scheduled Date:
Model: S36-7-6 B	Warranty Eff. Date: 02/25/2022	Date Expected:
Builder: Kevin Shanks	Order Date: 03/09/2023	Completion Date:
Warranty Rep: Ay, Stephanie		

Lot General Instructions

Work Order Instructions

Item No.	Description	Item Status	Cause/Resolution	Scheduled Date	Scheduled Time	Completion Date
0003	check 2 bedroom and 1 register in living room behind couch registers minimal air flow	In Process				

Vendor Signature: _____ Date: _____

Homeowner Signature: *[Signature]* Date: April 3/22

Original