

Closing Date: 06Oct22
Address: 32 Beatrice Drive
Wasaga Beach, Ontario
Location: Shoreline Point - Phase: 1 - Lot: 30
Today's Date: 06Jan23
Contact(s): Marius Slavescu - Home: (647) 569-2049 - (marius@slavescu.net)
Monica Slavescu - Home: (647) 569-2049 - (monica@slavescu.net)
Email: marius@slavescu.net

Company: Newmar
Attention: Alex
Telephone: (905) 672-1233
Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
153599	Interval	Foyer- General- front door not closing properly. strong draft coming through		Complete H/o didn't sign

Date Completed: March 31/23 Homeowner Signature: [Signature]
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: March 31/23 Trade &/or Service Tech.
Signature: [Signature]
Print Name: Steven Meice

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.



Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000633 City: WASAGA BEACH Received: Jan 10, 2023

Name: ZANCOR WASAGA SINGLES Service Phone(s): Time: Order: D379072-1

Service Fax: Lot#: 30 Phase: Phase: Phase:

Site Fax: Lot#: 30 Phase: Phase: Phase:

RESIDENT INFORMATION

Home Owner Name: MARIUS SLAVESCU Address: 32 BEATRICE DRIVE

Home Phone(s): 647-569-2049 Work Phone(s): Email(s): marius@slavescu.net

Cell Phone(s): Lot #: 30 Phase: Complete

LINKED ORDER INFORMATION (D379072-1)

Customer: N000633 ZANCOR WASAGA SINGLES

Model: 40-02 (CB)

SERVICE INSTRUCTIONS

FOYER- GENERAL- FRONT DOOR NOT CLOSING PROPERLY. STRONG DRAFT COMING THROUGH

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
1	200 5' 8" CLAD DOOR SYS weather stripping	FOY	OTHER RPLCMNT PARTS	72 X 97.75	CB 61316 FJ RIGHT 5' 8" CLAD DOOR SYS	1

Problem Description: No door sign Backup - wants door to sit perfectly
Flush with each other

☐ Warranty ☐ CHARGEABLES

Material \$ Material \$ NIC

Labour \$ Labour \$

P.O.#: P.O.#:

Cause: _____

Solution: Door seals + Lacks properly

Date Completed: March 30/23 Approved: _____

Time: 4:50pm Service Signature: [Signature] STEVE