



Zancor Homes (Wasaga) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 08 Dec 22

Address:

16 Simona Avenue

Wasaga Beach, Ontario

Shoreline Point - Phase: 1 - Lot: 118

Location:

05 Jan 23

Today's Date:

Contact(s):

Jean, Marie Ntawutarama - Cell: (416) 559-0666 - (jmntawutarama@gmail.com)

Amida Kabazayire Ntawutarama - Cell: (647) 393-7961 - (kabamida@yahoo.com)

Email:

jmntawutarama@gmail.com

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
152844	PDI	Exterior- General- far right garage transom glass has stress crack		complete
152926	Interval	Exterior- General- trim/filler in between front door and transom		complete

Date Completed: March 31/23

Homeowner Signature: [Signature]

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: March 31/23

Trade &/or Service Tech.

Signature: [Signature]

Print Name: Steven Ntaw

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be



Priority: Normal

Status: SCHEDULED

BUILDER

Customer: N000633

Name: ZANCOR WASAGA SINGLES

Service Fax:

Site Fax:

City: WASAGA BEACH

Service Phone(s):

Site Phone: 118

Lot#: 118

Received: Jan 12, 2023

Time: 10AM - 2PM

Order: D382326-1

Phase:

RESIDENT INFORMATION

Home Owner Name: JEAN MARIE NTAWUTARAMA

Address: 16 SIMONA AVE

Home Phone(s):

Work Phone(s):

Cell Phone(s): 416-559-0666, 647-393-7961

Email(s): jmntawutarama@gmail.com, kabamida@yahoo.com

LINKED ORDER INFORMATION (D382326-1)

Customer: N000633 ZANCOR WASAGA SINGLES

Lot #: 118

Model: 40-06 (CB)

Phase:

SERVICE INSTRUCTIONS

EXTERIOR- GENERAL- TRIM/FILLER IN BETWEEN FRONT DOOR AND TRANSOM

PLEASE CALL HALF HOUR BEFORE ARRIVAL 416-559-0666

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
140	M12 MULTI JOIN need 1" exterior joint cap cb	FOY	OTHER RPLCMNT PARTS	72 X 0.75	CB 61316 FJ *SHIP013	1
141	5' 8" CLAD DOOR SYS	FOY	OTHER RPLCMNT PARTS	72 X 97.75	CB 61316 FJ RIGHT 5' 8" CLAD DOOR SYS	1
142	E130_STYLE DOORLITE	FOY	OTHER RPLCMNT PARTS	20 X 80	E130_STYLE DOORLITE	2
143	WINDOW JOIN 2 PART	FOY	OTHER RPLCMNT PARTS	70.5 X 24	CB 61316 FJ	1
144	NEWMAR VINYL TRANSOM	FOY	OTHER RPLCMNT PARTS	35.25 X 24	CB 61316 FJ	1
145	NEWMAR VINYL TRANSOM	FOY	OTHER RPLCMNT PARTS	35.25 X 24	CB 61316 FJ	1

Problem Description:

W/o Supp Bedard

☐ Warranty

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Material \$

Labour \$

P.O.#:

Cause:


Solution:

Date Completed: March 3/23

Approved: _____

Time: 3:01pm

Service Signature: _____


STEVE



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 872-1233 FAX (905) 872-1076

WO # W176009
Pack Slip: 215666

Service Date: Jan 23, 2023

Priority: Normal

Status: PENDING

BUILDER

Customer: N000633

Name: ZANCOR WASAGA SINGLES

Service Fax:

Site Fax:

City: WASAGA BEACH

Received: Jan 12, 2023

Service Phone(s):

Time:

Site Phone:

Order: D382326-1

Lot#: 118

Phase:

RESIDENT INFORMATION

Home Owner Name: JEAN MARIE NTAWUTARAMA

Address: 16 SIMONA AVE

Home Phone(s):

Work Phone(s):

Cell Phone(s): 416-559-0666, 647-393-7961

Email(s): jmntawutarama@gmail.com,

kabamida@yahoo.com

LINKED ORDER INFORMATION (D382326-1)

Customer: N000633 ZANCOR WASAGA SINGLES

Lot #: 118

Model: 40-06 (CB)

Phase:

SERVICE INSTRUCTIONS

EXTERIOR- GENERAL- TRIM/FILLER IN BETWEEN FRONT DOOR AND TRANSOM

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
140	M12 MULTI JOIN JOIN CAP	FOY	OTHER RPLCMNT PARTS	72 X 0.75	CB 61316 FJ *SHIP013	1
141	5' 8" CLAD DOOR SYS	FOY	OTHER RPLCMNT PARTS	72 X 97.75	CB 61316 FJ RIGHT 5' 8" CLAD DOOR SYS	1
142	E130_STYLE DOORLITE	FOY	OTHER RPLCMNT PARTS	20 X 80	E130_STYLE DOORLITE	2
143	WINDOW JOIN 2 PART	FOY	OTHER RPLCMNT PARTS	70.5 X 24	CB 61316 FJ	1
144	NEWMAR VINYL TRANSOM	FOY	OTHER RPLCMNT PARTS	35.25 X 24	CB 61316 FJ	1
145	NEWMAR VINYL TRANSOM	FOY	OTHER RPLCMNT PARTS	35.25 X 24	CB 61316 FJ	1

Problem Description:

Walls given Regular front Cap

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

need 11 exterior front cap and front door

Date Completed:

Jan 23/23

Approved:

[Signature]