



Zancor Homes (Wasaga) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 20Oct22

Address: 27 Simona Avenue

Wasaga Beach, Ontario

Location: Shoreline Point - Phase: 1 - Lot: 147

Today's Date: 09Jan23

Contact(s): Vira Kynylyuk - Home: (416) 804-0861 - (verakynylyuk@rogers.com)
Petro Tverdokhib - Home: (607) 425-2667 - (petrotverdokhib@gmail.com)

Email: verakynylyuk@rogers.com

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
153556	30-Day	Exterior- General- Item #9 the sealant for the frosting coverage on outer door is not tight - water gets in and leaks		

Date Completed:

* Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed:

Trade &/or Service Tech.

Signature:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.



Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000633 City: WASAGA BEACH Received: Jan 12, 2023

Name: ZANCOR WASAGA SINGLES Service Phone(s): Time: 1ST CALL

Service Fax: Site Phone: Order: D383295-1

Site Fax: Lot#: 147 Phase:

RESIDENT INFORMATION

Home Owner Name: VIRA KYRYLYUK & PETER TVERDOKH Address: 27 SIMONA AVE

Home Phone(s): 416-804-0861 Work Phone(s):

Cell Phone(s): Email(s): verakyrylyuk@rogers.com

LINKED ORDER INFORMATION (D383295-1)

Customer: N000633 ZANCOR WASAGA SINGLES Lot #: 147

Model: 40-03 (WH)/LOT 147 Phase: Complete

SERVICE INSTRUCTIONS

THE SEALANT FOR THE FROSTING COVERAGE ON OUTER DOOR IS NOT TIGHT - WATER GETS IN AND LEAKS

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
151	E620_STYLE DOORLITE	FOY	FRAME ONLY	22 X 48		2

Problem Description: Backup signed by Hlo

☐ Warranty

☐ CHARGEABLES

Material \$ 159

Labour \$ 120

P.O.#:

Cause:

Solution:

Date Completed: March 31/23 Approved:

Time: 304am Service Signature: STEVE