Marranty Services

Marranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Key & Site. (olor: Bucki

Closing Date: 05Jun23

Address:

Location:

Caledon Club - Phase: 1B - Lot: 16B

Today's Date:

23Mar23

Contact(s): Email:

Company: **Perfect Touch Painting**

Attention:

John Hagithomas

Telephone:

(416) 399-2584

Fax:

(416) 929-0893

Please Complete the following items:

DAI	Туре	Issue	Appt. Date/Time	Notes
155105	PDI	Foyer- General- varnish required at trim at landing to basement	24Mar23 /am	DONE
155109	PDI	Exterior- General- painting not complete	24Mar23 /am	GENSONAL
155476	Interval	Stairs- General- stain/varnish required at nosing at 2nd floor due to Bolton repair	24Mar23 /am	DONE

Date Completed:

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Print Name: DAVE MADONAD

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

	to Bolton repair	• • • •	
Date Completed:		Homeowner Signature:	
		The Homeowner acknowledges and accepts all work has been completed in a workman like manner.	
Date Completed:		Trade &/or Service Tech.	
		Signature:	
		Print Name:	

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Caledon Club - Phase: 1B - Lot: 16B

155105 - 1 - Image - varnish required at trim at landing to basement

