

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W167702 Pack Slip:209298

Service Date: Apr 25, 2023

Priority: Normal Status: **SCHEDULED** RELEASED **BUILDER** Customer: N000508 City: WHITBY Received: Sep 19, 2022 Name: **ZANCOR WHITBY** Service Phone(s): Time: **1ST CALL** Service Fax: Site Phone: Order: D374354-1 Site Fax: Lot#: BLK 9 - 56 Phase: PH1 RESIDENT INFORMATION Home Owner Name: N/A 290 Address: N/A Home Phone(s): Work Phone(s): Cell Phone(s): Email(s): ryan6@hotmail.ca LINKED ORDER INFORMATION (D374354-1) Customer: N000508 ZANCOR WHITBY Lot #: BLK 9 - 56 Model: RLT-02 Phase: PH<sub>1</sub> SERVICE INSTRUCTIONS **OUTSTANDING:** FOYER/HALL- FRONT DOORS-DENT ON MAN DOOR PARTS REQUIRED LN Item Description Location Specification Size Options Qty 40 BUCKINGHAM PURCH, PATIO DOOR BKF OTHER RPLCMNT 71.5 X 95.5 **BK 61316 RIGHT** 1 vinyl capping **PARTS** BUCKINGHAM PURCH. **COMPLETED** PATIO DOOR 50 BUCKINGHAM PURCH, PATIO DOOR MB OTHER RPLCMNT 71.5 X 81.5 **BK 61316 RIGHT** vinyl capping **PARTS** BUCKINGHAM PURCH. **COMPLETED** PATIO DOOR 80 DOOR JOIN 2 PART **ENT** OTHER RPLCMNT 61.25 X 97.75 BK 61316 FJ 1 vinyl cladding **PARTS COMPLETED** 100 DCGH 2' 8" WOOD DOOR SYS G/H SLABS (ALL) 33.75 X 81.75 LEFT STEEL 600 SERIES 1 TYPE3 Problem Description: Warranty CHARGEABLES Material \$ Material \$ Labour \$ Labour \$ P.O.#: Cause: Solution: Date Completed: Approved:

| Time: | Service Signature: |      |  |
|-------|--------------------|------|--|
|       |                    | ALEX |  |



Normal

Priority:

**BUILDER** 

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

Status:



SCHEDULED

WO # W167702 Pack \$lip:209298

Service Date: Feb 15, 2023

| Customer:               | N000508                            | City:         | WHIT            | ГВҮ  | Received:                             | Sep 19, 2022 |
|-------------------------|------------------------------------|---------------|-----------------|--|---------------------------------------|--------------|
| Name:                   | ZANCOR WHITBY                      | Service       | Phone(s):       |  | Time:                                 | 10AM - 2PM   |
| Service Fax:            |                                    | Site Pho      | one:            |  | Order:                                | D374354·1    |
| Site Fax:               |                                    | Lot#:         | BLK             | 9 - 56   | Phase:                                | PH1          |
| RESIDENT                | INFORMATION                        |               |                 |  |                                       |              |
| Home Owner              | Name: N/A                          |               | Address:        | N/A  |                                       |              |
| Home Phone              | (s):                               |               | Work Phone(s):  |  |                                       |              |
| Cell Phone(s)           | :                                  |               | Email(s):       | ryan6@hotmail.   | .ca                                   |              |
| LINKED OR               | DER INFORMATION (D374354-1)        |               |                 |  |                                       |              |
| Customer:               | N000508 ZANCOR WHITBY              |               | Lo              | t #: BLK 9 - 56  | 3                                     |              |
| Model:                  | RLT-02                             |               | Ph              | nase: PH1  |                                       |              |
| SERVICE IN              | ISTRUCTIONS                        |               |                 |  |                                       |              |
| FOYER/HALL              | - FRONT DOOR DENT ON MAN DO        | OR FU         |                 |  |                                       |              |
| BEDROOM#                | 3- NOTE:-ADJUST WINDOW HARD T      | O OPEN        | mp              |  |                                       |              |
| EXTERIOR- F             | PAINT-SCRATCHES ON SLIDING BAI     | CONY DOOR     | TRIM AT EXTER   | RIOR RIGHT SIDE  | Comp                                  | 2            |
| EXTERIOR- F             | PAINT-SCRATCHES/ CHIPS ON DOO      | R TRIM RIGH   | T SIDE AT PATIC | ABOVE FRONT [  |                                       |              |
| MASTER BEI              | DROOM- WINDOWS-ADJUST BALCO        | NY DOOR       | comp            | ×  |                                       | /            |
| PARTS REC               | ription Locatio                    | be lead       | ation Sizo      | option op |                                       | pic. Alta    |
| 50 BUCKIN<br>vinyl cap  | GHAM PURCH. PATIO DOOR MB<br>oping | OTHE<br>PARTS | R RPLCMNT 71.5  | 5 X 81.5 BK 6<br>BUC   | 51316 RIGHT<br>CKINGHAM PU<br>IO DOOR | PRCH.        |
| 80 DOOR J<br>vinyl clad | OIN 2 PART ENT                     | OTHE<br>PARTS | R RPLCMNT 61.2  | 25 X 97.75 BK 6  | 81316 FJ                              | 1            |
| Problem Desc            | eription: need                     | Jour          | slab            | to ma  | m doo                                 | r            |
| Warranty                |                                    |               | CHARGEAB        | LES  |                                       |              |
| Material \$             |                                    |               | Material \$     |  |                                       | 1            |
| Labour \$               |                                    |               | Labour \$       |  |                                       | <i>k</i> .   |
|                         |                                    |               | P.O.#:          |  |                                       |              |
| Cause:                  |                                    |               |                 |  |                                       |              |
|                         |                                    |               |                 |  |                                       |              |
| Solution;               |                                    |               |                 | *  |                                       |              |
| Shonnessa Facev         | 02-10-2023 10:37 am                |               |                 |  |                                       |              |

| Date Completed: Febr. 15-23 | Approved:          | 112       |
|-----------------------------|--------------------|-----------|
| Time:                       | Service Signature: | THARMA 13 |



## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7600 AIRPORT ROAD, MISSISSAUGA, ON 14T 4G6 TEL (905) 672-1230 FAX (905) 672-1076 WO # W167702 Pack Slip:209298

Service Date: Feb 15, 2023

| newmar  | , | ,, , (,               |                         |             |                                     |              |     |
|---|---|-----------------------|-------------------------|-------------|-------------------------------------|--------------|-----|
| Priority: Normal                              |   | Status:               | SCHEDULED               | )           |                                     |              |     |
| BUILDER                                       |   |                       |                         |             |                                     |              |     |
| Customer: N000508                             |   | City:                 | WHITBY                  |             | Received                            | Sep 19, 2022 |     |
| Name: ZANCOR WHITBY                           |   | Service Phone(s):     |                         |             | Time:                               | 10AM - 2PM   |     |
| Service Fax:                                  |   | Site Phone:           |                         |             | Order:                              | D374354-1    |     |
| Site Fax:                                     |   | Lot#:                 | BLK 9 - 56              |             | Phase:                              | PH1          |     |
| RESIDENT INFORMATION                          |   |                       |                         |             |                                     |              |     |
| Home Owner Name: N/A                          |   | Address:              | N/A                     |             |                                     |              |     |
| Home Phone(s):                                |   | Work Pho              |                         |             |                                     |              |     |
| Cell Phone(s):                                |   | Email(s):             | ryan6                   | i@hotmail.c | a                                   |              |     |
| LINKED ORDER INFORMATION (D3743               | 354-1)                                  |                       |                         |             |                                     |              |     |
| Customer: N000508 ZANCOR WHITBY               |   |                       |                         | BLK 9 - 56  |                                     |              |     |
| Model: RLT-02                                 |   |                       | Phase:                  | PH1         |                                     |              |     |
| SERVICE INSTRUCTIONS                          |   |                       |                         |             |                                     |              |     |
| FOYER/HALL- FRONT DOORS-DENT ON M.            | AN DOOR                                 |                       |                         |             |                                     |              |     |
| BEDROOM #3- NOTE:-ADJUST WINDOW H.            | ARD TO OP                               | EN                    |                         |             |                                     |              |     |
| EXTERIOR- PAINT-SCRATCHES ON SLIDIN           | NG BALCON                               | Y DOOR TRIM AT E      | EXTERIOR RIC            | GHT SIDE    |                                     |              |     |
| EXTERIOR- PAINT-SCRATCHES/ CHIPS ON           | N DOOR TR                               | IM RIGHT SIDE AT      | PATIO ABOVE             | FRONT D     | OOR                                 |              |     |
| MASTER BEDROOM- WINDOWS-ADJUST E              | BALCONY D                               | OOR                   |                         |             |                                     |              |     |
| ADD:  |   |                       |                         |             |                                     |              |     |
| MAIN HALL- GENERAL MAIN FLOOR SOUT            | H WINDOW                                | LEAKINGPLEAS          | E INVESTIGAT            | TE          |                                     |              |     |
| PARTS REQUIRED                                |   |                       |                         | . —         |                                     |              |     |
| LN Item Description                           | Location                                | Specification         | Size                    | Option      | s                                   | Q            | lty |
| 40 BUCKINGHAM PURCH. PATIO DOOR vinyl capping | BKF                                     | OTHER RPLCMN<br>PARTS | IT 71.5 X 95.5          | BUCK        | I316 RIGHT<br>KINGHAM PUF           |              | 1   |
|   |   |                       |                         |             | D DOOR                              |              |     |
| 50 BUCKINGHAM PURCH, PATIO DOOR vinyl capping | МВ                                      | OTHER RPLCMN<br>PARTS | T 71.5 X 81.5           | BUCK        | 1316 RIGHT<br>(INGHAM PUF<br>D DOOR | КСН,         | 1   |
| 80 DOOR JOIN 2 PART vinyl cladding            | ENT                                     | OTHER RPLCMN<br>PARTS | IT 61. <b>2</b> 5 X 97. |             | 1316 FJ                             |              | 1   |
| Problem Description:                          |   |                       |                         |             |                                     |              |     |
| Warranty                                      |   | CHAR                  | GEABLES                 |             |                                     | 14           |     |
| Material \$                                   |   | Material \$           |                         | _           |                                     |              |     |
| Labour \$                                     |   | Labour \$             |                         | =           |                                     |              |     |
| Cause:  |   | P.O.#:                |                         |             |                                     |              |     |
| Solution:                                     |   | llo -                 |                         |             |                                     |              |     |

| Date Completed; | Approved:          |  |
|-----------------|--------------------|--|
| Time:           | Service Signature: |  |
|                 | THARMA             |  |



Phone: (905) 738-7010

Fax: (905) 738-5948

**Work Order** 

Closing Date: 25Aug22

Address:

Location:

Now Towns In Brooklin - Phase: 1 - Lot: Unit 56 (Block 9)

Today's Date:

01Dec22

Contact(s):

Ryan Jin Hei Li - Cell: (905) 621-2828 - (ryan6@hotmail.ca)

Email:

ryan6@hotmail.ca

Company:

Newmar

Attention:

Alex

Telephone:

(905) 672-1233

Fax:

(905) 672-6350

Please Complete the following items:

| DAI    | Туре     | Issue  | Appt.<br>Date/Time | Notes |
|--------|----------|--|--------------------|-------|
| 149624 | PDI      | BEDROOM #3-<br>NOTE:~ADJUST<br>WINDOW HARD TO<br>OPEN  | 16Dec22<br>/pm     |       |
| 149626 | PDI      | EXTERIOR-<br>PAINT~SCRATCHES<br>ON SLIDING<br>BALCONY DOOR<br>TRIM AT EXTERIOR<br>RIGHT SIDE       | 14Nov22<br>/pm     |       |
| 149627 | PDI      | EXTERIOR-<br>PAINT~SCRATCHES<br>/ CHIPS ON DOOR<br>TRIM RIGHT SIDE AT<br>PATIO ABOVE<br>FRONT DOOR | 16Dec22<br>/pm     |       |
| 149632 | PDI      | MASTER BEDROOM-<br>WINDOWS~ADJUST<br>BALCONY DOOR  | 16Dec22<br>/pm     |       |
| 149645 | PDI      | FOYER/HALL-<br>FRONT<br>DOORS~DENT ON<br>MAN DOOR  | 14Nov22<br>/pm     |       |
| 152698 | Interval | Main Hall- General-  |                    |       |

| Main floor south window leaking. |   |
|----------------------------------|---|
| Date Completed:                  | Homeowner Signature: The Homeowner acknowledges and accepts all work has been completed in a workman like manner. |
| Date Completed: Feli- 15 23      | Trade &/or Service Tech.  |
|                                  | Signature:  |
|                                  | Print Name: Jharma  |

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

## Now Towns In Brooklin - Phase: 1 - Lot: Unit 56 (Block 9)

149624 - 1 - NOTE:~ADJUST WINDOW HARD TO OPEN



149627 - 1 - PAINT~SCRATCHES / CHIPS ON DOOR TRIM RIGHT SIDE AT PATIO ABOVE FRONT DOOR



149645 - 1 - FRONT DOORS~DENT ON MAN



149626 - 1 - PAINT~SCRATCHES ON SLIDING BALCONY DOOR TRIM AT EXTERIOR RIGHT SIDE



149632 - 1 - WINDOWS~ADJUST BALCONY DOOR

