



Quality Sterling Group

REPAIR ORDER
733890



NC

BUILDER: Zancor Homes

JOB SITE: Belle Aire Shores PH3

Customer Code:

Job Number: 18648 Board Area:8

COMPLAINT DATE: 03/14/23

LOT: 76w

INSTALLER:

SCHEDULED DATE: 03/31/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE: PDI

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 728307

REPAIR DESC: Floor squeak at entrance to laundry room

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE: _____

SUPER'S/OWNER'S SIGNATURE: _____ DATE: _____

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



HEAD
PROTECTION



FOOT
PROTECTION



CLASS A
Compressed
Gas



CLASS B
Flammable and
combustible
material



CLASS C
Oxidizing
material



CLASS D
Material
Moderately
toxic
and
corrosive



CLASS D
Material
Moderately
toxic
and
corrosive



CLASS D
Material
Moderately
toxic
and
corrosive



CLASS E
Corrosive
Material



CLASS F
Extremely
Dangerous
Reactive
Material

INSTALLER SIGNATURE

DATE



Quality Sterling Group CARPET WORK ORDER

INSTALLER

CUTTING SHEET COPY



728307

INSTALL

REPRINT 1

BUILDER: Zancor Homes		PROJECT/JOB SITE Belle Aire Shores PH3		JOBID 18648		PBID PB210559	
ADDRESS/MAJOR INTERSECTION:		LOT/LOCATION: 76w		CUST: ZANC22			
CONTACT:		MODEL/OPTIONS: 42-05-FISHER Elev.B/C					
BOOKED DATE		INSTALL DATE 17-Feb-23		INSTALLER MARK AND JOE			
SUPPLIER:		P.O. NUMBER		P.O. DATE		P.O. DUE DATE	
BOARD: 8 - GTA		WORK TYPE: Residential		ORDER REF:		SALES PERSON: John Pacione	
ROOM	UNDERPAD	Carpet [COLOUR]	SIZE	NOTES			
Upper Hall	PK:30790 PLUS	PK:22283 Opening Night/TXP140 [20]					
Master Bed	PK:30790 PLUS	PK:22283 Opening Night/TXP140 [20]					
Bed 2	PK:30790 PLUS	PK:22283 Opening Night/TXP140 [20]					
Bed 3	PK:30790 PLUS	PK:22283 Opening Night/TXP140 [20]					
Bed 4	PK:30790 PLUS	PK:22283 Opening Night/TXP140 [20]					
Carpet Accessories		PK:5845 Transition LS40D - 0" -3/8" 4ft L box 20' 5 pieces [LS40D]					
INSTALLER NOTES		BASE	LABOUR	TOTAL YARDS			
		MOULDINGS	C.O.D.				

WARNINGTHINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHATHEAD
PROTECTIONFOOT
PROTECTIONCLASS A
Compressed
GasCLASS B
Flammable and
combustible
materialCLASS C
Oxidizing
materialCLASS D
Materials causing
immediate and
serious toxic
effectsCLASS D
Materials causing
other toxic effectsCLASS D
Bio hazardous
Infectious MaterialCLASS E
Corrosive
MaterialCLASS F
Dangerously
Reactive
Material

INSTALLER SIGNATURE

DATE



Quality Sterling Group

REPAIR ORDER
733890



NC

BUILDER: Zancor Homes

JOB SITE: Belle Aire Shores PH3

Customer Code:

Job Number: 18648 Board Area:8

COMPLAINT DATE: 03/14/23

LOT: 76w

INSTALLER:

SCHEDULED DATE: 03/31/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE: PDI

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 728307

REPAIR DESC: Floor squeak at entrance to laundry room

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

2 seams

INSTALLER'S SIGNATURE:

[Handwritten Signature]

SUPER'S/OWNER'S SIGNATURE:

DATE:

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

INSTALLER SIGNATURE

DATE



HEAD PROTECTION



FOOT PROTECTION



CLASS A
Compressed Gas



CLASS B
Flammable and
combustible
material



CLASS C
Oxidizing
material



CLASS D
Materials
which are
extremely
reactive



CLASS D
Materials
which are
extremely
reactive



CLASS D
Materials
which are
extremely
reactive



CLASS E
Corrosive
Material



CLASS F
Dangerous
Reactive
Material