



BUILDER:

**Zancor Homes** 

JOB SITE:

**Belle Aire Shores PH3** 

**Customer Code:** 

Job Number:

18648

Board Area:8

COMPLAINT DATE: 04/17/23

LOT:

356W

INSTALLER:

SCHEDULED DATE: 04/20/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

**ACCESS NOTES:** 

REPAIR TYPE:

PDI

REPAIRMAN:

**BUILDER WO#** 

**BUILDER PO#:** 

PO Required:

NO

Inspection Reqd:

NO

**ORIGINAL WO#:** 

735729

REPAIR DESC:

Upper hall - Adjust carpet at entrance to master left side bubbled

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

Melal Colo

SUPER'S/OWNER'S SIGNATURE:

DATE: 20 6 April 2023

NOTE\*\*\* Please have this memo signed by the owner or site super upon completion.

WARNING





















DATE

## Quality Sterling Group



BUILDER:

**Zancor Homes** 

JOB SITE:

**Belle Aire Shores PH3** 

**Customer Code:** 

Job Number:

18648

Board Area:8

COMPLAINT DATE: 04/17/23

LOT:

356W

**INSTALLER:** 

SCHEDULED DATE: 04/20/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

**ACCESS NOTES:** 

REPAIR TYPE:

PDI

REPAIRMAN:

**BUILDER PO#:** 

**BUILDER WO#** 

PO Required:

NO

Inspection Regd:

NO

**ORIGINAL WO#:** 

735729

REPAIR DESC:

Upper hall - Adjust carpet at entrance to master left side bubbled

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

Firesh carpet at dooways due to late Randwood installation Streach carpet at upper

INSTALLER'S SIGNATURE: \_\_

Milal Color

SUPER'S/OWNER'S SIGNATURE:

DATE: 200 April 2023

NOTE\*\*\* Please have this memo signed by the owner or site super upon completion.

WARNING THINK SAFETY - ALWAYS WEAR YOUR SAFETY SHOES AND HARDHAT

















INSTALLER SIGNATURE

DATE