

**Outstanding Deficiencies
For ZANCOR CALEDON-SITE LABOUR
For Caledon Club**

Work Order Date	Lot	Phase	Site	Type	Deficiency Description	DAI	Appointment Date	Days Out
22Feb23	58A	1	Caledon Club	PDI	Master Bedroom- General- FLOORING~FLOOR SQUEAK AT ENTRANCE TO MASTER AT ENTRANCE TO CLOSET	154720	NoAppoint.	65
28Mar23	Block 149 Unit 3	1	Caledon Club	PDI	Kitchen- General- remove paint splatters left of fridge from gable	155620	NoAppoint.	35
28Mar23	15B	1B	Caledon Club	PDI	Exterior- General- DENT ON MAN DOOR GARAGE	155568	NoAppoint.	31
28Mar23	15B	1B	Caledon Club	PDI	Family Room- General- no window handle installed at operating window	155593	NoAppoint.	31
28Mar23	15B	1B	Caledon Club	PDI	BASEMENT- NOTE:~ADJUST WINDOW LEFT OF LAUNDRY SINK	155564	NoAppoint.	31
28Mar23	15B	1B	Caledon Club	PDI	Basement- General- NOTE:~HOMEOWNER REQUESTING TO HAVE INSULATION HIGHER WHERE GARAGE WALL IS, BY CODE? NA	155563	NoAppoint.	31
20Apr23	143A	1	Caledon Club	PDI	Exterior- General- Crack at foundation wall on right side of house-H.O Requesting repair now	156317	NoAppoint.	8
20Apr23	143A	1	Caledon Club	PDI	Exterior- General- remove insulation at hood fan vent(INSIDE)	156328	NoAppoint.	8
20Apr23	143A	1	Caledon Club	PDI	Foyer- General- Svc to patch inside and outside of man door dented - Interior top left corner	156298	NoAppoint.	8
24Apr23	Block 153 Unit 1	1	Caledon Club	PDI	Basement- General- NOTE:~ONE BASEMENT WINDOW SCREEN NOT INSTALLED AT WINDOW BY ROUGH IN.	156520	NoAppoint.	4
27Apr23	39B	1B	Caledon Club	PDI	Bedroom 4- General- FLOORING~REMOVE DIRT OF CARPET IN FRONT OF WINDOW RIGHT SIDE	156612	NoAppoint.	1