



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W180532  
Pack Slip:222227

Service Date: May 10, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000531 City: CALEDON Received: Mar 10, 2023  
Name: ZANCOR CALEDON CLUB Service Phone(s): Time:  
Service Fax: Site Phone: Order: D385441-1  
Site Fax: Lot#: BLK149-1 Phase:

RESIDENT INFORMATION

Home Owner Name: Address:  
Home Phone(s): Work Phone(s):  
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D385441-1)

Customer: N000531 ZANCOR CALEDON CLUB Lot #: BLK149-1  
Model: RLTH-02 HIGHLAND (END) (CB) Phase:

SERVICE INSTRUCTIONS

154995-KITCHENWINDOWS-BALCONY SCREEN DOOR RIPPED BOTTOM  
LEFT CORNER

*Complete*

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
40	BUCKINGHAM PURCH. PATIO DOOR po 83026	BKF	SCREENS-REPLA CEMENT-DOORS	35.375 X 92.375	CB 61316 LEFT BUCKINGHAM PURCH. PATIO DOOR	1

Problem Description:

*no H/W yet to sign*

☐ Warranty

☐ CHARGEABLES

Material \$ \_\_\_\_\_

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

Labour \$ *NIC*

P.O.#: \_\_\_\_\_

Cause: \_\_\_\_\_

Solution: \_\_\_\_\_

Date Completed: *May 10/23*

Approved: *[Signature]*

Time: *15min*

Service Signature: *[Signature]*

STEVE



**Zancor Homes (Caledon) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 12Jun23

**Address:**

**Location:** Caledon Club - Phase: 1 - Lot: Block 149 Unit 1

**Today's Date:** 08Mar23

**Contact(s):**

**Email:**

**Company:** Newmar

**Attention:** Alex

**Telephone:** (905) 672-1233

**Fax:** (905) 672-6350

**Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
154995	PDI	KITCHEN- WINDOWS~BALCON Y SCREEN DOOR RIPPED BOTTOM LEFT CORNER			

**Date Completed:** \_\_\_\_\_

**Homeowner Signature:** \_\_\_\_\_

The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

**Date Completed:** Mar 10/23

**Trade &/or Service Tech.**

**Signature:** 

**Print Name:** Steven Maia

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

**Caledon Club - Phase: 1 - Lot: Block 149 Unit 1**

**154995 - 1 - WINDOWS~BALCONY SCREEN DOOR  
RIPPED BOTTOM LEFT CORNER**

