



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W183173
Pack Slip: 238558

Service Date: May 12, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Apr 06, 2023
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D390450-1
Site Fax: Lot#: 215W Phase: 3

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D390450-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 215W
Model: 50-03 CANAL/WH/LOT 215W Phase: 3

SERVICE INSTRUCTIONS

REPLACE THE WINDOW FRAME ONLY ON LINE: 263 (B3). AND CAP THE SIDE OF THE EXTERIOR VINYL FRAME ON LINE: 261 (B3).

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
261	NEWMAR VINYL CASEMENT FIXED capping	B3	OTHER RPLCMNT PARTS	27 X 52	WH 61316 FJ	1
263	NEWMAR VINYL CASEMENT	B3	FRAME ONLY	27 X 52	RIGHT WH 61316 FJ	1

Problem Description: BROKEN FRAME FROM THE OUTSIDE RIGHT SIDE

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ 143

Labour \$ 120

P.O.#:

Cause:

Solution: VINYL CAPPING - (PHOTO IS AVAILABLE IF NEEDED)

Date Completed: MAY 12, 2023

Approved:

Time:

Service Signature:

RAY

NOTE: NO ONE AVAILABLE FOR SIGNATURE